

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/EG123003494/ACY3Q2**Date:** 11/07/2023**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

**Claimant Vehicle No :** PC6694C **Insured Vehicle No :** GBJ6523S

Date of Loss: 29/03/2023 Nature of Claim: TP Claim No: CDMCG23000781

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **PC6694C**

Make & Model: TOYOTA HIACE, 3.0 (A) Engine No: 1KD2668229

Reg. Date: 13/10/2017 (Man. Year: 2016) Chassis No: KDH2230030293

Colour: White Odometer: 258471 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C

Front Left Side: Habilead 6 mm Rear Left Side: Habilead 6 mm

Front Right Side: Habilead 6 mm Rear Right Side: Habilead 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,973.42	2,379.00	594.42	19.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,750.00	1,240.00	1,510.00	54.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,723.42</b>	<b>3,619.00</b>	<b>2,104.42</b>	<b>36.77</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,900.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,723.42</b>	<b>2,900.00</b>	<b>2,823.42</b>	<b>49.33</b>

**INSPECTION**

Date of Assignment: 03/04/2023

Date Inspected: 05/04/2023 Inspected At: Automobile Hub Enterprise  
1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @  
KAKI BUKIT  
Singapore 417883

Estimated Period of Repair: 5.0 days

**Adjuster:** ADRIAN LING**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 10 Jul 2023)	
Parts:	N/A	TOYOTA HIACE 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC6694C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	479.80 FL	*479.80 FL
2	1		*REAR BUMPER SIDE HOLDER (O/S)	Damaged	58.40 FL	*58.40 FL
3	1		*TAILLAMP	Cracked	389.40 FL	*389.40 FL
4	1		*REAR BODY PANEL	Dented	1,715.90 FL	*1,715.90 FL
5	1		*REAR BODY PANEL AIR VENT	Not Necessary	45.90 FL	*- FL
6	1		*REAR MUDFLAP	Cut	128.50 FL	*128.50 FL
7	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
8	1		*REAR BODY PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
9	1		*REAR BODY PANEL GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
10	1		*REAR WHEEL RIM	Not Necessary	280.00 FS	*- FS
11	1		*REAR WHEEL RIM COVER	Cut	180.00 FS	*150.00 FS
12	1		*REAR TYRE	Not Necessary	250.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					3,677.90	3,072.00
- List Item Discount on L Items 25.00/25.00% (S\$)					704.48	693.00
Total Parts (S\$)					2,973.42	2,379.00
Report was unsubmitted during this print-out.						

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING ,REMOVE AND REFIT PARTS	New	1,000.00	600.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,000.00	300.00
3	WIRING CHECK	New	50.00	30.00
4	TO APPLY TUFF COAT	New	180.00	60.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE UPHOLSTERY	New	150.00	60.00
7	TO REMOVE REAR BODY PANEL GLASS	New	120.00	60.00
8	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
<b>Gross Labour Cost (S\$)</b>			<b>2,750.00</b>	<b>1,240.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >