

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS4/CTI23003495/KWP3M4**Date:** 19/04/2023**REFERENCE**

Insured/Claimant:	CHIANG CHIAN WEE (ZHANG JIANWEI)	Policy No:	DMPCSNW00170422200	Claim No:	SNM23D202401/C01/LEEPG
Date of Loss:	30/03/2023	Nature of Claim:	OD		

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SJQ5973B</b>				
Make & Model:	MITSUBISHI LANCER, 1.6 GLX 5MT AIRBAG 2WD (M)		Engine No:	4G18KC5475	
Reg. Date:	19/05/2009 (Man. Year: 2009)		Chassis No:	JMYSNCS3A9U004651	
Colour:	Metallic Blue		Odometer:	0 km	
Engine Capacity:	1584 cc				
Market Value/New Car Price:	S\$9,000.00				
Sum Insured (S\$):	<b>Market Value/New Car Price</b>				

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/55R15	Rear Tyre Size:	195/55R15
Front Left Side:	Bridgestone 3 mm	Rear Left Side:	Bridgestone 3 mm
Front Right Side:	Bridgestone 3 mm	Rear Right Side:	Bridgestone 3 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,235.00	4,445.00	3,790.00	46.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	546.00	546.00	0.00	0.00
Paintwork Labour	600.20	600.20	0.00	0.00
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,381.20</b>	<b>5,591.20</b>	<b>3,790.00</b>	<b>40.40</b>
<b>- Excess (S\$)</b>	<b>0.00</b>	<b>800.00</b>	<b>-800.00</b>	
<b>(S\$)</b>	<b>9,381.20</b>	<b>4,791.20</b>	<b>4,590.00</b>	<b>48.93</b>
<b>+ GST 8.00/8.00% (S\$)</b>	<b>750.50</b>	<b>383.30</b>	<b>367.20</b>	<b>48.93</b>
<b>Nett Amount (S\$)</b>	<b>10,131.70</b>	<b>5,174.50</b>	<b>4,957.20</b>	<b>48.93</b>

**INSPECTION**

Date of Assignment:	04/04/2023 Present Location:	Ding Auto Pte Ltd (HQ)
Date Inspected:	04/04/2023 Inspected At:	DING AUTO PTE LTD BLK 10 #01-20 SIN MING IND EST SEC C SINGAPORE 575645
Estimated Period of Repair:	6.0 days	

**Adjuster:** KENNETH KONG**Manager:** XinYu

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,210.00 NETT)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Apr 2023)
Parts:	143	mitsubishi lancer 1.6 glx 5mt airbag 2wd (m) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJQ5973B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS - TOTAL AMOUNT		8,235.00 F	*4,445.00 F
						F=Franchise part.
Total Parts (S\$)					8,235.00	4,445.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Paintwork Labour</b>				
1	Total Paint Labour	New	382.20	382.20
2	Total Paint Materials	New	218.00	218.00
<b>Labour Items</b>				
3	Total Panel/Mechanical Labour	New	546.00	546.00
<b>Gross Labour Cost (S\$)</b>			<b>1,146.20</b>	<b>1,146.20</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >