

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT HSBC LIFE (SINGAPORE) PTE LTD CS3/HSB23003512/Tnp3e2 Ref: 10 MARINA BOULEVARD Date: 15/05/2023 #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 Code: HSB ATTN: LOH CYNTHIA Policy Particulars :- (THIRD PARTY CLAIM) 1. SH 9984J CDQ 8371 Insured Veh. Veh. Inspected VFX/P2419138 0.00 Policy No. Coverage (\$) S3M04KUJ Claim No. Excess (\$) 0.00 LOH CYNTHIA 04/04/2023 **Assign From Assign Date** Vehicle Particulars & Condition 2. YAMAHA 0 Make & Model C.C HIDDEN **Engine No.** Year of Reg. WHITE Chassis No. Colour Odometer **IN ORDER** Steering **IN ORDER** NIL Modification **Brakes** GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre **DIAMONDS** 80/90 R17 5 mm L/H Front Tyre mm DIAMONDS 80/90 R17 R/H Rear Tyre 5 mm L/H Rear Tyre mm **Description of Damages** 4. THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY. 5. **General Information** 22/03/2023 **Inspect Date / Time** 05/04/2023 ( 12:30 PM ) **Accident Date** HUA CHIN (2000) TRADING MOTOR SVC CENTRE Survey held at 50, BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING SINGAPORE 659578 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

Report Ref No. CS3/HSB23003512/Tnp3e2

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000

**Estimate Days of Repair** 

Inspected By

5b.

**MOHAMAD TAUFIKH** 

K.K.LAU CPT(RET)

5 Working Days

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

ESTIMATED NORMAL PERIOD FOR REPAIR:

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser