



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI23003519/Apa3q2 Date: 28/06/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBK 1033S	Veh. Inspected	GBD 2327A	
Policy No.	DMCVSNW00145432201	Coverage (\$)	0.00	
Claim No.	SNM23D202379/C02/ GBK1033S/TANKL	Excess (\$)	0.00	
Assign From		Assign Date	04/04/2023	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV350	c.c	2488	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JN1MC2E26Z0002770	Colour	GREY	
Odometer	202467 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	BRIDGESTONE	6 mm	
L/H Front Tyre	195 R15C	BRIDGESTONE	6 mm	
R/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm	
L/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	29/03/2023	Inspection Date	30/03/2023	
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 2327A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	688.70	688.70
6	REAR BUMPER SIDE BRACKET CLIPS @\$11.30	NECESSARY	67.80	30.00
4	REAR BUMPER LOWER BRACKET @\$78.40	NOT NECESSARY	313.60	-
2	REAR BUMPER SIDE RETAINER @\$78.60	DAMAGED	157.20	157.20
1	REAR END PANEL (INNER)	TO REPAIR SEE LABOUR	558.60	-
1	REAR END PANEL (OUTER)	TO REPAIR SEE LABOUR	540.90	-
1	REAR END PANEL TOP PLATE	BENT	331.50	123.00
1	REAR END PANEL STEP PANEL	DENTED	350.60	350.60
1	REAR END PANEL TOP PANEL	NOT NECESSARY	121.80	-
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	2,284.50	-
1	REAR FLOOR PANEL RUBBER MAT	NOT NECESSARY	480.60	-
1	REAR SPARE TYRE CARRIER /BRACKET	NOT NECESSARY	432.60	-
2	REAR TAILLAMP @\$318.60	O/S CRACKED	637.20	318.60
2	REAR TAILLAMP LOWER PANEL @\$361.10	NOT NECESSARY	722.20	-
2	REAR TAILLAMP INNER PANEL @\$185.60	TO REPAIR SEE LABOUR	371.20	-
1	REAR TAILGATE	DISTORTED	2,454.80	2,101.00
1	REAR TAILGATE LOCK	DAMAGED	241.10	241.10
1	REAR TAILGATE LOCK CATCH	NOT NECESSARY	35.80	-
1	REAR TAILGATE LOCK CATCH	BENT	55.60	55.60
1	REAR TAILGATE INNER COVER PANEL	BENT	604.80	185.00
1	REAR TAILGATE INNER TRIM	DEFORMED	341.60	165.00
1	REAR TAILGATE OUTER CHROME	CRACKED	289.10	289.10
1	REAR TAILGATE EMBLEM LOGO	NECESSARY	45.60	45.60
1	REAR TAILGATE EMBLEM NV350	NECESSARY	77.40	77.40
1	REAR TAILGATE EMBLEM URVAN	NECESSARY	45.60	45.60
1	REAR WEATHERSTRIPE	CUT	110.60	110.60
1	REAR EXHAUST PIPE	NOT NECESSARY	986.30	-
	LESS 10% DISCOUNT		-1,334.73	-498.41
			12,012.57	4,485.69
	<u>SPECIAL NETT ITEMS</u>			
1	REAR TAILGATE OUTER SEAL (SN)	NOT NECESSARY	120.00	-

Report Ref No. CC6/CTI23003519/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR NUMBER PLATE WITH CASING (SN)	NOT NECESSARY	60.00	-
1	REAR TAILGATE WINDSCREEN GLASS SEALANT (SN)	NECESSARY	120.00	60.00
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	100.00	-
1	REAR BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	REAR REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	REAR STICKER 70KM/H (SN)	NECESSARY	40.00	15.00
1	REAR BUMPER TOP RUBBER PAD (SN)	NOT NECESSARY	150.00	-
1	SET REAR TAILLAMP OUTER GARNISH GUARD (SN)	NOT NECESSARY	220.00	-
1	REAR FLOOR PANEL PLY WOOD (SN)	CRACKED	650.00	250.00
			1,800.00	555.00
	LABOUR			
	LABOUR FOR PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR END PANEL (INNER),REAR END PANEL (OUTER),REAR FLOOR PANEL AND REAR TAILLAMP INNER PANEL.		1,600.00	800.00
	LABOUR FOR SPRAYPAINTING.		1,200.00	800.00
	WIRING CHECK.		80.00	30.00
	TO APPLY RUST PROOF /TUFF COAT ON ACCIDENT AREAS .		200.00	40.00
	LABOUR FOR REMOVE & TRANSFER ALL REAR TAILGATE FITTING.		200.00	60.00
	LABOUR FOR REMOVE & RENEW REAR EXHAUST PIPE ,STRAIGHTEN & REPAIR .	NOT NECESSARY	300.00	-
	LABOUR FOR REMOVE & REFIX REAR WINDSCREEN GLASS .		150.00	120.00
	LABOUR FOR REMOVE AND REFIT REVERSE SENSOR.		100.00	50.00
			3,830.00	1,900.00
GRAND TOTAL			17,642.57	6,940.69
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,500.00

Report Ref No. CC6/CTI23003519/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBD 2327A

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBD 2327A

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

