

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATEDATE: 03.04.2023

GBH5941K

INSURANCE: INCOME (45)MODEL: Hyundai IoniqSURVEYOR: LKK-VEHICLE NO.: SHB6616DMVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$ 459.40
	Rear Bumper Reinforcement	1		\$ 394.80
	Rear Bumper Reinforcement Bracket RH/LH	2	\$ 138.10	\$ 276.20
	Rear Bumper Centre Moulding	1		\$ 451.25
	Rear Bumper Clips	10	\$ 2.20	\$ 22.00
	Rear Bumper Reflector Lamp LH	1		\$ 41.45
	Rear Bumper Tow Cover	1		\$ 98.80
	Rear Bumper FogLamp	1		\$ 201.50
	Rear Smart Key Antenna	1		\$ 40.50
	SUB TOTAL			\$ 1,985.90
	LESS 20%			\$ 397.18
	DISCOUNTED TOTAL			\$ 1,588.72
	Reverse Sensors	1		\$ 180.00
	Rear No.Plake With Trim Cover	1		\$ 55.00
				\$ 235.00
	LESS 10%			\$ 23.50
	S/NETT TOTAL			\$ 211.50
	SPARE PARTS TOTAL			\$ 1,800.22
	Labour Charge			
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 300.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 820.00
	ESTIMATE TOTAL			\$ 2,620.22

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

XR
?XSVL
?XSVL
✓DEF
XNW
?XSVL
✓SCR
✓SCR
?XSVL
/not working
/CRA

350
250
30

NA2 LKIC
314/2023 1555
LIS
2 DMS
CHECK ITEM PHOTO
AFTER REPAIR PHOTO