

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4447T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	CRACKED	458.60	458.60
1	REAR BUMPER LOWER COVER	DEFORMED	552.60	552.60
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	318.80	-
1	REAR BUMPER UNDER SIDE COVERLH	TO REPAIR SEE LABOUR	232.00	-
1	REAR BUMPER SIDE RETAINER LH/RH	SERVICEABLE	112.70	-
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
	LESS 25% DISCOUNT		-424.18	-258.30
			1,272.52	774.90
	NETT ITEMS			
1	BUMPER REVERSE SENSOR (N)	SERVICEABLE	135.70	-
	LESS 10% DISCOUNT		-13.57	-
			122.13	-
	SPECIAL NETT ITEMS			
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER UNDER SIDE COVERLH.		600.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	CHECK LIGHTING.	NOT NECESSARY	60.00	-
	REMOVE/REFIX REVERSE SENSOR.		60.00	30.00
			1,020.00	630.00
	GRAND TOTAL		2,464.65	1,454.90





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,150.00
(TO ITS PRE-ACCIDENT CONDITION)		·
(CONFIRMED)		

Report Ref No. NS/INC23003527/Nqy3m4

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

h

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser