

ASS. REC. BY:

REF: TU / 23003536 / ky

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Thion HLT

of 6367

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 78k

IDAC Accident Rport: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMK 9782E Yr Regn: 09, 19

Type: (H) Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: (A) Hyundai Avante S.c.c 1591

Colour: M. Bl A/C: Insured / Std / Nil / NA

Sp. Reading: 56425 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: MM140841cmku 882930

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

WETAKE

Front _____ Rear _____

R/Bal. 9 mm R/Bal. 9 mm

L/Bal. 9 mm L/Bal. 9 mm

D.O.A. 4/4/23 D.O.I. 5/4/2023

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

Rear & 13M

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>Est not ready</u>
<u>2/1/24 6/15pm @ 12,400h</u>	<u>Call</u>

Date/Time, File Pass to? : Prell. Report : Final Report

Days Of Repair: _____ Resurvey No. of Trlp: _____

1) _____ Date/Time, File Return to? _____

2) _____

Add Fee: : Site Insp (\$) : Interview (\$) : Tech Invs (\$) : Weekend (\$)

Survey Fee:	_____
Transportation	_____
S - RS - SI	_____
Fuel	_____
Others	_____
TOTAL	_____

Report Format : _____ Lump Sum / I.B.I: (\$ _____)


Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
 Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

Not Withheld
21km @ 12,400/h
Return After Paint
12 days

Make/Model: HYUNDAI AVANTE
 Engine/Chassis No.: KMHD841CMKU882930
 Date of accident: 04.04.23
 Damaged area: Front & Rear

Date: 10/04/2023
 Claim Type: TP
 VRN: SMK9782E



List items					
S/N	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Rear Bumper <i>500.10</i>	<i>R</i> 1	\$ 983.00	\$ 983.00	✓
2	Rear Bumper lower moulding <i>333.50</i>	<i>CM</i> 1	\$ 567.00	\$ 567.00	✓
3	Rear Bumper lower cowling	<i>N/S</i> 1	\$ 314.00	\$ 314.00	X
4	Rear Bumper reflector lamp <i>0188</i>	<i>N/S CM</i> 2	\$ 255.00	\$ 510.00	X
5	Rear Bumper lower side cowling	<i>R</i> 2	\$ 135.00	\$ 270.00	X
6	Rear Bumper impact absorber	<i>CM</i> 1	\$ 166.00	\$ 166.00	X
7	Rear Bumper reinforcement	<i>R</i> 1	\$ 559.00	\$ 559.00	X
8	Rear Bumper side support	<i>N/S</i> 2	\$ 89.00	\$ 178.00	X
9	Rear Side retainer	<i>N/S</i> 2	\$ 65.00	\$ 130.00	X
10	Front fender	<i>R</i> 2	\$ 860.00	\$ 1,720.00	X
11	Front fender cowling	<i>R</i> 2	\$ 196.00	\$ 392.00	X
12	Taillamp <i>0951-20 N/S M/C</i>	<i>015</i> 2	\$ 661.00	\$ 1,322.00	X
13	Taillamp weatherseal sponge	<i>R</i> 2	\$ 16.00	\$ 32.00	X
14	End panel <i>520.60</i>	<i>R</i> 1	\$ 632.00	\$ 632.00	✓
15	End panel top garnish <i>150</i>	<i>M/C</i> 1	\$ 227.00	\$ 227.00	✓
16	Spare wheel top board	<i>R</i> 1	\$ 396.00	\$ 396.00	X
17	Rear floor panel	<i>R</i> 1	\$ 884.00	\$ 884.00	X
18	Bootlid <i>1782</i>	<i>R</i> 1	\$ 1,785.00	\$ 1,785.00	✓
19	Bootlid inner trim	<i>S</i> 1	\$ 149.00	\$ 149.00	X
20	Bootlid lock	<i>R</i> 1	\$ 224.00	\$ 224.00	X
21	Bootlid lock striker	<i>R</i> 1	\$ 56.00	\$ 56.00	X
22	Bootlid "AVANTE" emblem	<i>M</i> 1	\$ 53.00	\$ 53.00	✓
23	Bootlid "Hyundai" logo <i>38</i>	<i>M</i> 1	\$ 269.00	\$ 269.00	✓
24	Bootlid lamp	<i>S</i> 2	\$ 479.00	\$ 958.00	X
25	Side air vent	<i>S</i> 2	\$ 48.00	\$ 96.00	X
26	Exhaust assy	<i>R</i> 1	\$ 989.00	\$ 989.00	X
27	Exhaust mounting	<i>S</i> 2	\$ 35.00	\$ 70.00	X
28	Exhaust bracket	<i>R</i> 2	\$ 44.00	\$ 88.00	X
29	Exhaust heatshield	<i>R</i> 1	\$ 118.00	\$ 118.00	X
30	Rear licence plate lamp	<i>S</i> 2	\$ 143.00	\$ 286.00	X
31	Rear bumper tow cover	<i>R</i> 1	\$ 39.00	\$ 39.00	X
32	Rear fender inner trim	<i>S</i> 2	\$ 331.00	\$ 662.00	X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Repair Estimate

33	Bonnet	B1	1	\$ 1,253.00	\$ 1,253.00	✓
34	Bonnet insulator	Sm	1	\$ 225.00	\$ 225.00	X
35	Front bumper	494.40 B1	1	\$ 981.00	\$ 981.00	✓
36	Front bumper side retainer	MJ017	2	\$ 55.00	\$ 110.00	✓
37	Front bumper inner bracket	R	2	\$ 129.00	\$ 258.00	✓
38	Radiator grille	CM	1	\$ 525.00	\$ 525.00	✓
39	Radiator grille "HYUNDAI" logo	MC	1	\$ 55.00	\$ 55.00	✓
40	Front bumper lower grille	173.20 CM	1	\$ 387.00	\$ 387.00	✓
41	Front licence plate base	B1	1	\$ 106.00	\$ 106.00	✓
42	Headlamp	01501A MJS	CM2	\$ 1,645.00	\$ 3,290.00	✓
43	Headlamp lower bracket	015011	2	\$ 59.00	\$ 118.00	✓
44	Front bumper tow cover	Sm	1	\$ 49.00	\$ 49.00	X
45	Front bumper base cover	Sm	1	\$ 214.00	\$ 214.00	X
46	Front foglamp	Sm	2	\$ 329.00	\$ 658.00	X
47	Front foglamp outer garnish	Sm	2	\$ 179.00	\$ 358.00	X
48	Bootlid "S" emblem	MC	1	\$ 45.00	\$ 45.00	✓
49	Support panel frame	CM	1	\$ 745.00	\$ 745.00	✓
50	Support panel top garnish	CM	1	\$ 198.00	\$ 198.00	✓
51	Headlamp panel	R	2	\$ 104.00	\$ 208.00	X
52	A/C condenser	746 R1	1	\$ 948.00	\$ 948.00	✓
53	A/C condenser side deflector	CM	2	\$ 139.00	\$ 278.00	✓
54	Rear windscreen moulding	MC	1	\$ 129.00	\$ 129.00	X
55	Radiator	710.50 B1	1	\$ 1,035.00	\$ 1,035.00	✓
56	Radiator fan assy	578 CM	1	\$ 865.00	\$ 865.00	✓
57	Bonnet hinge	69.60 M17	1	\$ 145.00	\$ 145.00	✓
58	Keyless antenna	Sm	1	\$ 216.00	\$ 216.00	✓
59	Bootlid weatherstrip	01	1	\$ 195.00	\$ 195.00	✓
60	Front bumper lower beam	M1P	1	\$ 198.00	\$ 198.00	X
61	Front bumper reinforcement	230 CM	1	\$ 593.00	\$ 593.00	✓
62	Front bumper sponge	CM M1P	1	\$ 162.00	\$ 162.00	✓
63	Front bumper lower deflector	Sm	1	\$ 372.00	\$ 372.00	✓
64	Subframe bracket	C181 R1	2	\$ 265.00	\$ 530.00	✓
65	Parking assist wire harness	Sm	1	\$ 429.00	\$ 429.00	X
Subtotal					\$ 31,002.00	
List discount					20.00%	
Total					\$ 24,801.60	

Special nett items					
No.	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Rear Bumper clips	MC 12	\$ 5.50	\$ 66.00	✓
2	Rear fender cowling clips	MC 8	\$ 5.50	\$ 44.00	X
3	Taillamp clips	MC 8	\$ 5.50	\$ 44.00	X
4	Reverse sensor	MC 1	\$ 280.00	\$ 280.00	2005n
5	End panel sealant	MC 1	\$ 120.00	\$ 120.00	301n
6	End panel top garnish clips	MC 6	\$ 5.50	\$ 33.00	✓
7	Rear floor panel sealant	MC 1	\$ 150.00	\$ 150.00	X
8	Bootlid inner trim clips	MC 8	\$ 5.50	\$ 44.00	X
9	Rear fender inner trim clips	MC 16	\$ 5.50	\$ 88.00	X

Repair Estimate

10	Bonnet insulator clips	<i>NN</i>	8	\$ 5.50	\$ 44.00	X
11	Front bumper clips	<i>NN</i>	10	\$ 5.50	\$ 55.00	X
12	Front licence plate & frame	<i>BY</i>	1	\$ 55.00	\$ 55.00	455N-
13	Rear licence plate & frame	<i>RD</i>	1	\$ 55.00	\$ 55.00	455a
14	Reverse camera	<i>SN</i>	1	\$ 450.00	\$ 450.00	X
15	Rear windscreen sealant	<i>NN</i>	1	\$ 80.00	\$ 80.00	X
16	Sundries	<i>NN</i>	1	\$ 50.00	\$ 50.00	X
Total					\$ 1,658.00	

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew rear accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	8	\$ 1,600.00
2	To disconnect rear wire harness of electrical component to facilitate repairs, reconnect and check functions.	0.25	\$ 50.00
3	To remove and refit rear interior upholstery, inner trim, inner garnish, mouldings to facilitate the repair.	0.5	\$ 100.00
4	Supply spray paint material and necessary items to respray rear affected area / panel.	7	\$ 1,400.00
5	To dismantle / renew front accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	8	\$ 1,600.00
6	Supply spray paint material and necessary items to respray front affected area / panel.	7	\$ 1,400.00
7	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check functions.	0.25	\$ 50.00
8	To align rear chassis frame and to conduct chassis alignment on Car-O-Liner.	1.75	\$ <i>NN</i> 350.00
9	To rust proof accident affected portions.	1	\$ 200.00
Total labour			\$ 6,750.00

Estimate Grand Total	\$ 33,209.60
-----------------------------	---------------------

X
X
455N-
455a
X
X
X

1 800
200
600
800
600
600
200
X
900