

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Synergy@kb 25 Kaki Bukit Road 4 #01-60/61
Singapore 417800

Tel: 67023113 Fax: 67023773 Email: YTKB


INSURER : LONPAC INSURANCE BHD

PARTICULARS OF CLAIM			
Claim Type:	TP	Ref. No:	
Policy No:	5127640729	Date of Loss:	19/01/2023
Vehicle Reg. No.:	GBD8844J	Driveable?	no
Driver Age:	06/06/2023	Third Party Vehicle No.:	PMA5799
Any Injuries?	no	Contact No:	63166536
Insured/Claimant:	EBENEZER NDT	Driver:	BOOMI MUGESH
	SERVICES PTE LTD		
PARTS MODEL			
Make/Model:	Isuzu, CXZ81K	Vehicle Reg. Date:	
Vehicle Colour:		Engine Number:	
Chassis No:	LVPRPB4B3NC890295	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

DESCRIPTION OF ACCIDENT/LOSS	
Description of Accident/loss	
Remarks:	
Present Location:	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)-YTKB

COST OF CLAIMS	Amount
Parts	3,825.00
Miscellaneous Items	385.00
Labour	1,090.00
Paintwork Labour	860.00
Towing	0.00
Gross Total(S\$):	6,160.00
GST 7.00%(S\$):	431.20
Nett Amount(S\$):	6,591.20

This claim is handled by: Shaun Toh L M



REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER	580.00	-10.00	522.00 <i>de</i>
2	1	BOOT LID	900.00	-10.00	810.00 <i>bt</i>
3	1	REAR BUMPER SIDE RETAINER LH	80.00	-10.00	72.00 <i>?</i>
4	1	REAR BUMPER SIDE RETAINER RH	80.00	-10.00	72.00 <i>?</i>
5	1	REAR BUMPER REFLECTOR LH	75.00	-10.00	67.50 <i>x</i>
6	1	REAR BUMPER REFLECTOR RH	75.00	-10.00	67.50 <i>?</i>
7	1	REAR TAILLAMP RH	380.00	-10.00	342.00 <i>x</i>
8	1	REAR TAILLAMP LH	380.00	-10.00	342.00 <i>x</i>
9	1	REAR TAILGATE LOCK	320.00	-10.00	288.00 <i>?</i>
10	1	REAR END PANEL	1,100.00	-10.00	990.00 <i>Ry</i>
11	1	REAR WINDSCREEN MOULDING	280.00	-10.00	252.00 <i>ne</i>
Total Parts (S\$)					3,825.00

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER CLIPS	30.00	0.00	30.00 <i>ne</i>
2	1	REAR REVERSE SENSOR	200.00	0.00	200.00 <i>rw</i>
3	1	70KM/H STICKER	30.00	0.00	30.00 <i>ne</i>
4	1	8 PAX STICKER	30.00	0.00	30.00 <i>ne</i>
5	1	REAR WINDSCREEN SEALANT	60.00	0.00	60.00 <i>ne</i>
6	1	REAR NUMBER PLATE	35.00	0.00	35.00 <i>x</i>
Sub Total (S\$)					385.00

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	800.00	0.00	800.00 <i>600</i>
2	1	To Transfer Rear Tailgate.	80.00	0.00	80.00 <i>60</i>
3	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	0.00	30.00 <i>✓</i>
4	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	0.00	100.00 <i>✓</i>
5	1	To Remove and Refit Rear Bumper Sensor.	80.00	0.00	80.00 <i>30</i>
Gross Labour Cost (S\$)					1,090.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	800.00	0.00	800.00 <i>600</i>
2	1	To Supply Spray Terostat Sealant On The	30.00	0.00	30.00 <i>✓</i>

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
		Cutting Areas.			
3	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	30.00	0.00	30.00

Gross Labour Cost (S\$) 860.00

< END OF ESTIMATES >

Tanjil 97445749 / 62563561
 'WP' 12/4/23 @ 10am.
 2/5 Resing after repair.
 5 days
 tanjil @ khawp.com