

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT HSBC LIFE (SINGAPORE) PTE LTD Ref: CS3/HSB23003550/Twp3e2 10 MARINA BOULEVARD #48-01 MARINA BAY Date: 31/05/2023 FINANCIAL CENTRE TOWER 2 SINGAPORE ATTN: LOW GARNET Code: HSB Policy Particulars :- (THIRD PARTY CLAIM) 1. SHD 8568K **FBT 2343T** Insured Veh. Veh. Inspected VFX/P2419140 0.00 Policy No. Coverage (\$) S3M04L40 0.00 Claim No. Excess (\$) LOW GARNET 05/04/2023 **Assign Date** Assign From 2. **Vehicle Particulars & Condition** YAMAHA XMAX Make & Model 292 C.C **HIDDEN Engine No.** Year of Reg. 2021 **GREY** Chassis No. MH3SH182111016259 Colour Odometer **IN ORDER** Steering **IN ORDER** NIL Modification **Brakes** GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 120/70 R15 **PIRELLI** 5 mm L/H Front Tyre mm PIRELLI 150/70 R14 R/H Rear Tyre 5 mm L/H Rear Tyre mm **Description of Damages** 4. THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION. 5. **General Information** 30/03/2023 Inspect Date / Time 05/04/2023 (01:19 PM) **Accident Date** HIGH SPEED GARAGE PTE. LTD. Survey held at 5 SOON LEE STREET #01-07 PIONEER POINT SINGAPORE 627607 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000

Report Ref No. CS3/HSB23003550/Twp3e2

Estimate Days of Repair

Inspected By

5b.

MOHAMAD TAUFIKH

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

6 Working Days

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser