

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: LIBERTY	DATE	: 03/04/2023
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:	NKE1657223120	
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SNC3600S		
MODEL	: TOYOTA COROLLA AXIO 1.5X CVT ABS D/AIRBAG 2WD		
CHASSIS NO		Veron	
<u>ACCIDENT DETAILS</u>		DATE	: 2-Apr-23
		TIME	: 11:40HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOT LID <i>Dented</i>	1	\$ 921.40	\$ 921.40
2	BOOT LID LOGO <i>New</i>	1	\$ 90.00	\$ 90.00
3	BOOT LID EMBLEM "COROLLA AXIO" <i>New</i>	1	\$ 62.00	\$ 62.00
4	BOOT LID EMBLEM "HYBRID" <i>New</i>	1	\$ 70.00	\$ 70.00
5	BOOT LID HINGE <i>New</i>	2	\$ 110.50	\$ 221.00
6	BOOT LID LOCK <i>Dented</i>	1	\$ 210.50	\$ 210.50
7	BOOT LID OUTER CHROME <i>New</i>	1	\$ 280.60	\$ 280.60
8	BOOT LID WEATRHERSTRIP <i>At cut</i>	1	\$ 255.30	\$ 255.30
9	REAR BUMPER <i>Distorted</i>	1	\$ 674.90	\$ 674.90
10	REAR BUMPER SIDE RETAINER <i>New</i>	2	\$ 62.40	\$ 124.80
11	REAR BUMPER BRACKET <i>New</i>	2	\$ 80.00	\$ 160.00
12	REAR BUMPER REFLECTOR <i>New</i>	2	\$ 90.00	\$ 180.00
13	TAIL LAMP <i>Cracked</i>	2	\$ 648.50	\$ 1,297.00
14	TAIL LAMP PANEL <i>Repis</i>	2	\$ 280.00	\$ 560.00
15	TAIL LAMP LOWER BRACKET <i>Cracked</i>	2	\$ 56.80	\$ 113.60
16	REAR FENDER <i>Repis</i>	2	\$ 1,495.20	\$ 2,990.40
17	REAR FENDER INNER TRIM <i>RH torn</i>	2	\$ 320.50	\$ 641.00
18	WINDSCREEN MOULDING <i>New</i>	1	\$ 160.20	\$ 160.20

19	REAR END PANEL <i>Dented</i>	1	\$ 826.80	\$ 826.80 <i>3.682</i>
20	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 175.00	\$ 175.00
21	REAR FLOOR PANEL <i>Riv</i>	1	\$ 980.50	\$ 980.50
22	REAR FLOOR PANEL TOP BOARD <i>Dented</i>	1	\$ 420.00	\$ 420.00 <i>285</i>
			TOTAL PRICE	\$ 11,415.00
			LESS 25%	\$ 2,853.75
			SUB TOTAL PRICE	\$ 8,561.25

4820.20
3615.15

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Dented</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIPS (SET) <i>New</i>	1	\$ 20.00	\$ 20.00
3	TAILLAMP CLIPS (SET) <i>New</i>	1	\$ 20.00	\$ 20.00
4	REAR FENDER INNRT TRIM CLIPS(SET) <i>New</i>	1	\$ 20.00	\$ 20.00
5	REAR WINDSCREEN SEALANT <i>New</i>	1	\$ 120.00	\$ 120.00
6	REAR END PANEL TOP GARNISH CLIPS (SET) <i>New</i>	1	\$ 20.00	\$ 20.00 <i>10</i>
7	REAR END PANEL INSULATION SEAL <i>New</i>	1	\$ 120.00	\$ 120.00 <i>60</i>
8	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00 <i>20</i>
			TOTAL	\$ 540.00

380

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,000.00	700 <i>900</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,000.00	1000	
3	TUFF COAT	\$ 250.00	60	
4	WIRING CHECK	\$ 180.00	30	
5	TO REMOVE REAR WINDSCREEN TO FACILITATE FENDER REPAIR	\$ 250.00	X	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 180.00	50	
7	TRANSFER BOOTLID MECHANISM	\$ 180.00	60	
8	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X	

TOTAL

\$5,120.00

2100

ESTIMATE REPORT

TOTAL PARTS COST : \$ 9,101.25
TOTAL LABOUR COST : \$ 5,120.00
TOTAL REPAIR COST : \$ 14,221.25

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

PART BY PART / LUMP SUM :

NO OF DAYS :

FAX :

Adrian Ling.

1/s 04/04/23.

07 ~~08~~ Days.

total: 6095.15

1/s: 4850

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Authorised by Repairer