

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS6/AIS23003554/HVP3M4**Date:** 19/04/2023**REFERENCE**

Insured/Claimant: CHARISSPEED INTERNATIONAL Policy No: AIS/2022/0000394/000147
Date of Loss: 31/03/2023 Nature of Claim: OD Claim No: 202332006869

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YQ8959X**
Make & Model: HINO XZU710R, 4.0 D 14FT WID CAB 5T MT (M) Engine No: N04CWN20660
Reg. Date: 30/11/2022 (Man. Year: 2022) Chassis No: JHHUCV3F80K047655
Colour: White Odometer: 10578 km
Engine Capacity: 4009 cc
Market Value/New Car Price: S\$125,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: Rear Tyre Size:
Front Left Side: 5 mm Rear Left Side: 5 mm
Front Right Side: 5 mm Rear Right Side: 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,607.00	2,277.00	330.00	12.66
Miscellaneous Items	25.00	25.00	0.00	0.00
Labour	1,350.00	1,100.00	250.00	18.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,982.00	3,402.00	580.00	14.57
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	3,382.00	2,802.00	580.00	17.15
+ GST 8.00/8.00% (S\$)	270.56	224.16	46.40	17.15
Nett Amount (S\$)	3,652.56	3,026.16	626.40	17.15

INSPECTION

Date of Assignment: 05/04/2023 Present Location: City Auto Pte Ltd (HQ)
Date Inspected: 05/04/2023 Inspected At: City Auto Pte Ltd (HQ)
160 Sin Ming Drive #05-01, Sin Ming AutoCity,
Singapore 575722
Estimated Period of Repair: 5.0 days

Adjuster: Edward**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 19 Apr 2023)	
Parts:	N/A	HINO XZU710R 4.0 D 14FT WID CAB 5T MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YQ8959X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front panel (WCP)	Buckled	350.00 F	*350.00 F
2	1		*Front grille (WCP)	Dented	250.00 F	*250.00 F
3	1		*Front grille emblem (WCP)	Missing	75.00 F	*75.00 F
4	1		*Front bumper (WCP)	Deformed	250.00 F	*250.00 F
5	1		*Front bumper reinforcement (WCP)	Bent	280.00 F	*280.00 F
6	1		*Front bumper bracket 2PIECES (WCP)	O/s Cracked	370.00 F	*185.00 F
7	1		*RH headlamp (WCP)	Cracked	550.00 F	*550.00 F
8	1		*RH foglamp (WCP)	Not Necessary	115.00 F	*- F
9	1		*Hino emblem (WCP)	Necessary	65.00 F	*65.00 F
10	1		*300 emblem (WCP)	Necessary	65.00 F	*65.00 F
F=Franchise part.						
					Sub Total (S\$)	2,370.00 2,070.00
					+ Margin on L,N Items 10.00/10.00% (S\$)	237.00 207.00
					Total Parts (S\$)	2,607.00 2,277.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Number plate (Bent)	25.00	25.00
Sub Total (\$\$)			25.00	25.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	- To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	New	600.00	500.00
2	- Spray painting on affected and replace parts	New	750.00	600.00
Gross Labour Cost (\$\$)			1,350.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >