4/17/23, 10:51 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIS23003559/UWY3Q2

17/04/2023 Date:

REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No:

Claimant Vehicle SLH934X Insured Vehicle No: SNA4755H No:

Date of Loss: 01/04/2023 Nature of Claim: TP Claim No: 2023 32006802FR

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLH934X

MITSUBISHI ATTRAGE, 1.2 (A) Make & Model: 3A92UDN2474 Engine No:

Reg. Date: 24/10/2016 (Man. Year: 2016) Chassis No: MMBSTA13AHH003384

Colour: Odometer: 257523 km Red

Engine Capacity: 1193 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15 185/55 R15 Rear Tyre Size: Front Left Side: Habilead 6 mm Rear Left Side: Habilead 6 mm Front Right Side: Habilead 6 mm Rear Right Side: Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		8,989.60	3,488.00	5,501.60	61.20
Miscellaneous Items		0.00	0.00	0.00	
Labour		3,560.00	1,530.00	2,030.00	57.02
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	12,549.60	5,018.00	7,531.60	60.01
	Approved Total (Overridden) (S\$)		4,000.00		
	Nett Amount (S\$)	12,549.60	4,000.00	8,549.60	68.13

INSPECTION

Date of Assignment: 04/04/2023

Imperium Automotive - Kaki Bukit (HQ) Date Inspected: 04/04/2023 Inspected At:

25 Kaki Bukit Road 4, #01-49 Synergy@KB

Singapore 417800

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Apr 2023)

Parts: 143 MITSUBISHI ATTRAGE 1.2 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLH934X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	777.00 FN	*- FN
2	1		*FRONT HEADLAMP -RH	Holder Cracked	1,891.00 FN	*1,233.00 FN
3	1		*FRONT GRILLE	Not Necessary	247.00 FN	*- FN
4	1		*FRONT GRILLE LOGO	Not Necessary	43.00 FN	*- FN
5	1		*FRONT BUMPER	Deformed / Torn	825.00 FN	*721.00 FN
6	1		*FRONT BUMPER CHROME MOULDING	Not fitted	476.00 FN	*- FN
7	1		*FRONT BUMPER FOG LAMP (O/S)	Cracked	486.00 FN	*315.00 FN
8	1		*FRONT BUMPER FOG LAMP GRILLE (O/S)	Scratched	38.00 FN	*38.00 FN
9	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	65.00 FN	*- FN
10	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	329.00 FN	*- FN
11	1		*FRONT BUMPER SIDE RETAINER (O/S)	Cracked	28.00 FN	*28.00 FN
12	1		*FRONT FENDER -RH	Dented / Bent	591.00 FN	*473.00 FN
13	1		*FRONT FENDER CHROME MOULDING	Not Necessary	95.00 FN	*- FN
14	1		*FRONT FENDER INNER SHIELD	Not Necessary	98.00 FN	*- FN
15	1		*FRONT FENDER LOWER BRACKET	Not Necessary	46.00 FN	*- FN
16	1		*FRONT FENDER TOP GARNISH	Not Necessary	105.00 FN	*- FN
17	1		*FRONT SUPPORT PANEL	Repair	879.00 FN	*- FN
18	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	112.00 FN	*- FN
19	1		*FRONT WHEEL HUB	No such part	164.00 FN	*- FN
20	1		*FRONT WHEEL BEARING	Damaged	128.00 FN	*128.00 FN
21	1		*FRONT SHOCK ABSORBER	Not Necessary	383.00 FN	*- FN
22	1		*FRONT KNUCKLE ARM	Bent	284.00 FN	*284.00 FN
23	1		*FRONT LOWER ARM	Not Necessary	268.00 FN	*- FN
24	1		*FRONT WIPER TANK	Not Necessary	86.00 FN	*- FN
25	1		*SET FRONT BUMPER CLIP	Necessary	45.00 FS	*40.00 FS
26	1		*FRONT NUMBER PLATE WITH HOLDER	Not Necessary	50.00 FS	*- FS
27	1		*SET FRONT FENDER INNER SHIELD CLIP	Not Necessary	45.00 FS	*- FS
28	1		*FRONT TYRE	Serviceable	400.00 FS	*-FS
29	1		*FRONT WHEEL RIM -RH	Warped	850.00 FS	*550.00 FS
F=Fra	nchise	part. S=SpcN	lett. N=NettItemDisc.			
				Sub Total (S\$)	9,834.00	3,810.00
	- Nett Item Discount on N Items 10.00/10.00% (S\$)				844.40	322.00
				Total Parts (S\$)	8,989.60	3,488.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	G New	80.00	20.00
2	TO REMOVE AND REFIT FRONT UNDERCARRIAGE	New	250.00	120.00
3	TO CONDUCT WHEEL ALIGNMENT	New	150.00	60.00
4	TO APPLY UNDERCOATING	New	180.00	30.00
5	PANEL BEATING	New	1,500.00	520.00
6	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,400.00	780.00
		Gross Labour Cost (S\$)	3,560.00	1,530.00
	Report was unsubm	itted during this print-out.		

< END OF ESTIMATES >