

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS23003561/KNP3Q2**Date:** 25/04/2023**REFERENCE**

Insured/Claimant:	PROTESINGAPORE	Policy No:	SP2003487196	
Date of Loss:	02/04/2023	Nature of Claim:	OD	Claim No: 202332006944

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNB5801X		
Make & Model:	TOYOTA COROLLA AXIO, 1.5 HYBRID CVT (A)	Engine No:	1NZ9304759
Reg. Date:	30/08/2021 (Man. Year: 2021)	Chassis No:	NKE1657245475
Colour:	Metallic Silver	Odometer:	188657 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$118,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	INTERTRAC 3 mm	Rear Left Side:	INTERTRAC 8 mm
Front Right Side:	INTERTRAC 3 mm	Rear Right Side:	INTERTRAC 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,592.00	6,457.00	3,135.00	32.68
Miscellaneous Items	635.00	150.00	485.00	76.38
Labour	2,710.00	2,310.00	400.00	14.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,937.00	8,917.00	4,020.00	31.07
Approved Total (Overridden) (S\$)		6,250.00		
- Excess (S\$)	0.00	2,000.00	-2,000.00	
(S\$)	12,937.00	4,250.00	8,687.00	67.15
+ GST 8.00/8.00% (S\$)	1,034.96	340.00	694.96	67.15
Nett Amount (S\$)	13,971.96	4,590.00	9,381.96	67.15

INSPECTION

Date of Assignment:	05/04/2023	Present Location:	Ding Auto Pte Ltd (HQ)
Date Inspected:	06/04/2023	Inspected At:	Ding Auto Pte Ltd (HQ)
			176 Sin Ming Drive #04-06, Sin Ming Autocare
			Singapore 575721
Estimated Period of Repair:	8.0 days		

Adjuster: KENNETH KONG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Apr 2023)

Parts: 143 TOYOTA COROLLA AXIO 1.5 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNB5801X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Bent	320.00 F	*320.00 F
2	1		*FRONT BUMPER SUPPORT (WCP)	Bent	180.00 F	*180.00 F
3	1		*FRONT BUMPER SPONGE (WCP)	Broken	65.00 F	*65.00 F
4	1		*FRONT BUMPER RETAINER RH (WCP)	Cracked	45.00 F	*45.00 F
5	1		*FRONT BUMPER RETAINER LH (WCP)	Serviceable	45.00 F	*- F
6	1		*FRONT BUMPER LOWER GARNISH (WCP)	Serviceable	145.00 F	*- F
7	1		*FRONT BUMPER SIDE COVER RH (WCP)	Dented	70.00 F	*70.00 F
8	1		*FRONT BUMPER SIDE COVER LH (WCP)	Serviceable	70.00 F	*- F
9	1		*FRONT BUMPER TOW CAP (WCP)	Dented	30.00 F	*30.00 F
10	1		*BONNET (WCP)	Bent	355.00 F	*355.00 F
11	1		*BONNET HINGE RH (WCP)	Bent	40.00 F	*40.00 F
12	1		*BONNET HINGE LH (WCP)	Distorted	40.00 F	*40.00 F
13	1		*BONNET INSULATOR (WCP)	No such part	205.00 F	*- F
14	1		*BONNET SATND (WCP)	Repair	65.00 F	*- F
15	1		*BONNET LOCK (WCP)	Distorted	60.00 F	*60.00 F
16	1		*FRONT GRILLE CPL (WCP)	Mtg Cracked	350.00 F	*350.00 F
17	1		*FRONT GRILLE CTR BRACKET (WCP)	Repair	90.00 F	*- F
18	1		*FRONT GRILLE BADGE (WCP)	Necessary	55.00 F	*55.00 F
19	1		*FRONT LOWER GRILLE (WCP)	Serviceable	180.00 F	*- F
20	1		*FRONT SUPPORT PANEL CPL (WCP)	Bent	520.00 F	*520.00 F
21	1		*FRONT PANEL UPPER GARNISH (WCP)	Distorted	145.00 F	*145.00 F
22	1		*HEADLAMP ASSY RH (WCP)	Broken	430.00 F	*430.00 F
23	1		*HEADLAMP ASSY LH (WCP)	Mtg Cracked	430.00 F	*430.00 F
24	1		*HEADLAMP UPPER CHROME TRIM RH (WCP)	Dented	105.00 F	*105.00 F
25	1		*HEADLAMP UPPER CHROME TRIM LH (WCP)	Serviceable	105.00 F	*- F
26	1		*HEADLAMP BRACKET RH (WCP)	Bent	65.00 F	*65.00 F
27	1		*HEADLAMP BRACKET LH (WCP)	Serviceable	65.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*FRONT FENDER RH (WCP)	Buckled	285.00 F	*285.00 F
29	1		*FRONT FENDER BRACKET RH (WCP)	Distorted	65.00 F	*65.00 F
30	1		*FRONT FENDER INNER SHIELD RH (WCP)	Distorted	110.00 F	*110.00 F
31	1		*RADIATOR ASSY (WCP)	Serviceable	790.00 F	*- F
32	1		*RADIATOR AIR GUIDE RH (WCP)	Cracked	85.00 F	*85.00 F
33	1		*RADIATOR AIR GUIDE LH (WCP)	Serviceable	85.00 F	*- F
34	1		*CONDENSOR ASSY (WCP)	Punctured	780.00 F	*780.00 F
35	1		*SUCTION HOSE (WCP)	Dented	250.00 F	*250.00 F
36	1		*DISCHARGE HOSE (WCP)	Dented	275.00 F	*275.00 F
37	1		*WASHER TANK (WCP)	Dented	85.00 F	*85.00 F
38	1		*WASHER PUMP (WCP)	Dented	90.00 F	*90.00 F
39	1		*AIR CLEANER HOUSING CPL (WCP)	Cracked	175.00 F	*175.00 F
40	1		*AIR DUCT (WCP)	Dented	55.00 F	*55.00 F
41	1		*AIR HOSE (WCP)	Serviceable	55.00 F	*- F
42	1		*FAN SHROUD CPL (WCP)	Serviceable	190.00 F	*- F
43	1		*FAN BLADE (WCP)	Serviceable	45.00 F	*- F
44	1		*FAN BLADE - RADIATOR (WCP)	Serviceable	45.00 F	*- F
45	1		*FAN MOTOR (WCP)	Serviceable	215.00 F	*- F
46	1		*FAN MOTOR - RADIATOR (WCP)	Serviceable	215.00 F	*- F
47	1		*FRONT WHEELHOUSE REINF RH (WCP)	Repair	240.00 F	*- F
Supplementary #1						
48	1		*AIR CLEANER FILTER (WCP)	Distorted	25.00 F	*25.00 F
49	1		*WIPER COWL PANEL (WCP)	Cracked	285.00 F	*285.00 F

F=Franchise part.

Sub Total (S\$)	8,720.00	5,870.00
+ Margin on L,N Items 10.00/10.00% (S\$)	872.00	587.00
Total Parts (S\$)	9,592.00	6,457.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT CAR PLATE & FRAME (Serviceable)	35.00	0.00
2	1	FRT BUMPER, FRT GRILLE, INNER SHIELD, PANEL & GARNISH - CLIPS (Necessary)	150.00	150.00
3	1	HEADLAMP/RADAR SENSOR - DIAGNOSIS & RE-SETTING (Not Necessary)	450.00	0.00
Sub Total (\$\$)			635.00	150.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR, PANEL BEAT AND STRAIGHTEN/ALIGN - ACCIDENT AREA	New	1,200.00	1,000.00
2	SPRAY PAINT - FRT BUMPER, FRT GRILLE, BONNET, FRT FENDER X2, FRT DOOR RH & SUPPORT PANEL	New	1,200.00	1,000.00
3	ALIGN HEADLAMP/RADAR SENSOR & TEST WIRING	New	150.00	60.00
4	REFILL - RADIATOR COOLANT	New	80.00	50.00
5	REFILL - AIR COND GAS	New	80.00	80.00
6	REPAIR & ALIGN -RH WHEEL HOUSE REINF	New	-	120.00
Gross Labour Cost (\$\$)			2,710.00	2,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >