

Ding Auto Pte Ltd (Co.Reg.No:201311788Z)176 Sin Ming Drive #04-06, Sin Ming Autocare
Singapore 575721

Tel: 64521208 Fax: 64520614 Email: ding@dingauto.sg;kenneth.ding@dingauto.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2003487196	Date of Loss:	02/04/2023
Vehicle Reg. No.:	SNB5801X	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	PROTESINGAPORE		
Driver:	NG MUN HIM		

Make/Model:	TOYOTA COROLLA AXIO, 1.5 HYBRID CVT (A)	Vehicle Reg. Date:	30/08/2021
Vehicle Colour:	SILVER		
Engine No:	1NZ9304759	Chassis No:	NKE1657245475
Odometer:	188657 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	12		

Present Location: DING AUTO PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	9,251.00
Miscellaneous Items	635.00
Labour	2,710.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	12,596.00
+ GST 8.00% (\$\$)	1,007.68
Nett Amount (\$\$)	13,603.68

This claim is handled by: HENRY LEE YOON SANG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 05 Apr 2023)**Parts:** 143 TOYOTA COROLLA AXIO 1.5 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Ding Auto Pte Ltd/SNB5801X/05/04/2023 12:31**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	*320.00 F
2	1		*FRONT BUMPER SUPPORT	0.00	0.00	*180.00 F
3	1		*FRONT BUMPER SPONGE	0.00	0.00	*65.00 F
4	1		*FRONT BUMPER RETAINER RH	0.00	0.00	*45.00 F
5	1		*FRONT BUMPER RETAINER LH	0.00	0.00	*45.00 F
6	1		*FRONT BUMPER LOWER GARNISH	0.00	0.00	*145.00 F
7	1		*FRONT BUMPER SIDE COVER RH	0.00	0.00	*70.00 F
8	1		*FRONT BUMPER SIDE COVER LH	0.00	0.00	*70.00 F
9	1		*FRONT BUMPER TOW CAP	0.00	0.00	*30.00 F
10	1		*BONNET	0.00	0.00	*355.00 F
11	1		*BONNET HINGE RH	0.00	0.00	*40.00 F
12	1		*BONNET HINGE LH	0.00	0.00	*40.00 F
13	1		*BONNET INSULATOR	0.00	0.00	*205.00 F
14	1		*BONNET SATND	0.00	0.00	*65.00 F
15	1		*BONNET LOCK	0.00	0.00	*60.00 F
16	1		*FRONT GRILLE CPL	0.00	0.00	*350.00 F
17	1		*FRONT GRILLE CTR BRACKET	0.00	0.00	*90.00 F
18	1		*FRONT GRILLE BADGE	0.00	0.00	*55.00 F
19	1		*FRONT LOWER GRILLE	0.00	0.00	*180.00 F
20	1		*FRONT SUPPORT PANEL CPL	0.00	0.00	*520.00 F
21	1		*FRONT PANEL UPPER GARNISH	0.00	0.00	*145.00 F
22	1		*HEADLAMP ASSY RH	0.00	0.00	*430.00 F
23	1		*HEADLAMP ASSY LH	0.00	0.00	*430.00 F
24	1		*HEADLAMP UPPER CHROME TRIM RH	0.00	0.00	*105.00 F
25	1		*HEADLAMP UPPER CHROME TRIM LH	0.00	0.00	*105.00 F
26	1		*HEADLAMP BRACKET RH	0.00	0.00	*65.00 F
27	1		*HEADLAMP BRACKET LH	0.00	0.00	*65.00 F
28	1		*FRONT FENDER RH	0.00	0.00	*285.00 F
29	1		*FRONT FENDER BRACKET RH	0.00	0.00	*65.00 F
30	1		*FRONT FENDER INNER SHIELD RH	0.00	0.00	*110.00 F
31	1		*RADIATOR ASSY	0.00	0.00	*790.00 F
32	1		*RADIATOR AIR GUIDE RH	0.00	0.00	*85.00 F
33	1		*RADIATOR AIR GUIDE LH	0.00	0.00	*85.00 F
34	1		*CONDENSOR ASSY	0.00	0.00	*780.00 F
35	1		*SUCTION HOSE	0.00	0.00	*250.00 F
36	1		*DISCHARGE HOSE	0.00	0.00	*275.00 F
37	1		*WASHER TANK	0.00	0.00	*85.00 F
38	1		*WASHER PUMP	0.00	0.00	*90.00 F
39	1		*AIR CLEANER HOUSING CPL	0.00	0.00	*175.00 F
40	1		*AIR DUCT	0.00	0.00	*55.00 F
41	1		*AIR HOSE	0.00	0.00	*55.00 F

Ding Auto Pte Ltd/SNB5801X/05/04/2023 12:31. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
42	1		*FAN SHROUD CPL	0.00	0.00	*190.00 F
43	1		*FAN BLADE	0.00	0.00	*45.00 F
44	1		*FAN BLADE - RADIATOR	0.00	0.00	*45.00 F
45	1		*FAN MOTOR	0.00	0.00	*215.00 F
46	1		*FAN MOTOR - RADIATOR	0.00	0.00	*215.00 F
47	1		*FRONT WHEELHOUSE REINF RH	0.00	0.00	*240.00 F

F=Franchise part.

Sub Total (\$)	8,410.00
+ Margin on L,N Items 10.00% (\$)	841.00
Total Parts (\$)	9,251.00

Ding Auto Pte Ltd/SNB5801X/05/04/2023 12:31. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT CAR PLATE & FRAME	35.00
2	1	FRT BUMPER, FRT GRILLE, INNER SHIELD, PANEL & GARNISH - CLIPS	150.00
3	1	HEADLAMP/RADAR SENSOR - DIAGNOSIS & RE-SETTING	450.00
Sub Total (S\$)			635.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	REPAIR, PANEL BEAT AND STRAIGHTEN/ALIGN - ACCIDENT AREA	New	1,200.00
2	SPRAY PAINT - FRT BUMPER, FRT GRILLE, BONNET, FRT FENDER X2, FRT DOOR RH & SUPPORT PANEL	New	1,200.00
3	ALIGN HEADLAMP/RADAR SENSOR & TEST WIRING	New	150.00
4	REFILL - RADIATOR COOLANT	New	80.00
5	REFILL - AIR COND GAS	New	80.00
Gross Labour Cost (S\$)			2,710.00

Ding Auto Pte Ltd/SNB5801X/05/04/2023 12:31. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >