



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## OPINION ON REPAIR COST FOR VEHICLE NO. SLH 5485S

Qty	Description of Parts	Condition	Recommended (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>		
1	REAR BUMPER LOWER	CRACKED	745.10
1	REAR BUMPER CLIPS	NECESSARY	30.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	-
1	TAILGATE	DAMAGED	1,122.60
1	TAILGATE GLASS MOULDING	NECESSARY	-
1	TAILGATE GLASS SEALANT	NECESSARY	50.00
1	TAILGATE LOCK	DAMAGED	145.00
1	TAILGATE INNER BOARD	BROKEN	175.50
1	TAILGATE WEATHERSTRIP	CRACKED	189.00
1	TAILGATE SENSOR	CRACKED	80.00
1	TAILGATE "VEZEL" EMBLEM	NECESSARY	75.00
1	TAILGATE "HYBRID" EMBLEM	NECESSARY	90.00
	LESS 20% DISCOUNT		-540.44
			2,161.76
	<b><u>SPECIAL NETT ITEMS</u></b>		
1	REVERSE SENSOR (SN)	DAMAGED	200.00
			200.00
	<b><u>LABOUR</u></b>		
	PANEL. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		600.00
	RESPRAY.		400.00
	R & I TAILGATE GLASS.		120.00
	SENSOR.		50.00
			1,170.00
<b>GRAND TOTAL</b>			<b>3,531.76</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>	<b>2,800.00</b>
---	-----------------

Report Ref No. CS3/SPF23003564/Wqy3m4

**NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$2,800-\$3,500**

MUHAMMAD AKID BIN MOHAMED KAMAL

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.