



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23003565/Uvy3e2 Date: 14/04/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBK 2267C	Veh. Inspected	SJX 1800G
Policy No.		Coverage (\$)	0.00
Claim No.	D23001159MFCV	Excess (\$)	0.00
Assign From	JOANNE TAN	Assign Date	04/04/2023
2. Vehicle Particulars & Condition			
Make & Model	B.M.W. X3 (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WBATR12050LC94385	Colour	WHITE
Odometer	59755 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/50 R19	PIRELLI	6 mm
L/H Front Tyre	245/50 R19	PIRELLI	6 mm
R/H Rear Tyre	245/50 R19	PIRELLI	6 mm
L/H Rear Tyre	245/50 R19	PIRELLI	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	31/03/2023	Inspection Date	10/04/2023
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	