

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI23003566/AVY3E2**Date:** 28/06/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLK3519B**Insured Vehicle No :** SKX9838J

Date of Loss: 03/04/2023

Nature of Claim: TP

Claim No: CDMPG23000805

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLK3519B**

Make & Model: HONDA SHUTTLE, 1.5 G CVT (A)

Engine No: L15B5000532

Reg. Date: 13/01/2017 (Man. Year: 2016)

Chassis No: GK81100467

Colour: Black

Odometer: 231584 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15

Rear Tyre Size: 195/60 R15

Front Left Side: Wanli 6 mm

Rear Left Side: Wanli 6 mm

Front Right Side: Wanli 6 mm

Rear Right Side: Wanli 6 mm

*The above values represent the remaining tyre treads depth*COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,693.68	6,015.44	2,678.24	30.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,280.00	2,090.00	1,190.00	36.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,973.68	8,105.44	3,868.24	32.31
Approved Total (Overridden) (S\$)		6,500.00		
(S\$)	11,973.68	6,500.00	5,473.68	45.71
+ GST 8.00/8.00% (S\$)	957.89	520.00	437.89	45.71
Nett Amount (S\$)	12,931.57	7,020.00	5,911.57	45.71

INSPECTION

Date of Assignment: 05/04/2023

Date Inspected: 06/04/2023

Inspected At:

Modern Automotive Pte Ltd (HQ)

Blk 3023A Ubi Road 1, #01-61 & #01-58

Singapore 408717

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Jun 2023)	
Parts:	N/A	HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK3519B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	986.90 FL	*986.90 FL
2	2		*REAR BUMPER REFLECTOR	Not Necessary	90.40 FL	*- FL
3	2		*REAR BUMPER REFLECTOR GARNISH	Deformed	90.80 FL	*90.80 FL
4	1		*REAR BUMPER TOWING COVER	Not Necessary	19.00 FL	*- FL
5	2		*REAR BUMPER SIDE RETAINER	Necessary	64.00 FL	*64.00 FL
6	2		*REAR BUMPER SIDE SPONGE	Cracked	94.00 FL	*94.00 FL
7	1		*TAILGATE	Dented	1,193.20 FL	*1,193.20 FL
8	1		*TAILGATE OUTER CHROME MOULDING	Not Necessary	383.80 FL	*- FL
9	1		*TAILGATE LOGO	Not Necessary	38.40 FL	*- FL
10	1		*TAILGATE SHUTTLE EMBLEM	Not Necessary	55.40 FL	*- FL
11	1		*TAILGATE LAMP	N/S Cut	761.80 FL	*380.90 FL
12	1		*TAILGATE INNER LOCK	Damaged	298.40 FL	*298.40 FL
13	1		*TAILGATE LOCK CATCH	Not Necessary	24.00 FL	*- FL
14	1		*TAILGATE WEATHERSTRIPE	Cut	166.50 FL	*166.50 FL
15	1		*TAILGATE LOCK ANTENNA	Not Necessary	180.20 FL	*- FL
16	1		*TAILGATE INNER TRIM BOARD	Deformed	320.40 FL	*320.40 FL
17	1		*TAILGATE WINDSCREEN MOULDING	Necessary	149.20 FL	*149.20 FL
18	1		*TAILGATE BUZZER	Not Necessary	170.00 FL	*- FL
19	1		*TAILLAMP	N/S Cut	1,041.00 FL	*520.50 FL
20	1		*REAR END PANEL	Dented	681.20 FL	*681.20 FL
21	1		*REAR END PANEL TOP GARNISH	Deformed	155.00 FL	*155.00 FL
22	1		*REAR FLOOR PANEL TOP OUTER BOARD	Not Necessary	585.20 FL	*- FL
23	1		*REAR PLASTIC STORAGE BOX	Deformed	495.00 FL	*495.00 FL
24	1		*REAR TOOLS SPONGE TRAY	Cracked	265.40 FL	*265.40 FL
25	1		*REAR JACK COVER	Deformed	122.40 FL	*122.40 FL
26	2		*REAR FENDER INNER TRIM BOARD	Deformed	798.00 FL	*798.00 FL
27	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
28	1		*SET TAILGATE OUTER CHROME MOULDING CLIPS	Not Necessary	30.00 FS	*- FS
29	1		*TAILGATE WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
30	1		*SET TAIL LAMP CLIPS	Necessary	20.00 FS	*10.00 FS
31	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
32	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
33	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
34	1		*REAR CAMERA	Not Necessary	480.00 FS	*- FS
35	1		*TAILGATE SURROUND MOULDING	Necessary	250.00 FS	*150.00 FS
36	1		*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,539.60	7,371.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,845.92	1,356.36
Total Parts (\$\$)	8,693.68	6,015.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	1,200.00	800.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	1,200.00	800.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	80.00
5	TO REMOVE UPHOLSTERY	New	150.00	80.00
6	TO REMOVE TAILGATE GLASS	New	180.00	120.00
7	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
8	TO REMOVE REVERSE SENSOR	New	100.00	50.00
9	TO REMOVE REAR CAMERA	New	100.00	50.00
Gross Labour Cost (\$\$)			3,280.00	2,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >