

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG23003567/WVY3M4**Date:** 24/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220128255
Claimant Vehicle No :	FBQ9960G	Insured Vehicle No :	SNJ8188X
Date of Loss:	30/03/2023	Nature of Claim:	TP
		Claim No:	6800187207SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBQ9960G	Engine No:	KF61E1006736
Make & Model:	HONDA ADV150, 149cc ABS CVT	Chassis No:	MH1KF6112KK006787
Reg. Date:	23/01/2020 (Man. Year: 2019)	Odometer:	5665 km
Colour:	Red		
Engine Capacity:	149 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/80 R14	Rear Tyre Size:	130/70 R13
Front Left Side:	Federal 6 mm	Rear Left Side:	Federal 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	05/04/2023	LIAN CHIN HENG MOTOR & CARRIAGE PTE LTD
Date Inspected:	06/04/2023 Inspected At:	BLK 22 WOODLANDS LINK
		#01-35 SINGAPORE 738734
Estimated Period of Repair:	3.0 days	

Adjuster: Mohdakid**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$13,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*SIDE FAIRING O/S	Scratched	0.00 F	*- F	
2	1		*EXHAUST MUFFLER HEAT SHIELD	Scratched	0.00 F	*- F	
3	1		*COVER STEP PANEL O/S	Broken	0.00 F	*- F	
4	1		*FLOORBOARD O/S	Scratched	0.00 F	*- F	
					Total Parts (\$\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >