



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 8635Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT SIDE MIRROR (N/S)	CRACKED	599.00	599.00
1	FRT SIDE MIRROR COVER (N/S)	MISSING	55.00	55.00
1	FRT FRONT DOOR WINDOW GLASS (N/S)	PITTED	280.00	280.00
	LESS 15% DISCOUNT		-140.10	-140.10
			793.90	793.90
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT DOOR WINDOW GLASS SOLAR FILM (N/S) (SN)	NECESSARY	200.00	120.00
			200.00	120.00
	<u>LABOUR</u>			
	TO RESPRAY SIDE MIRROR .		180.00	60.00
	TO RENEW DAMAGED PARTS.		280.00	150.00
			460.00	210.00
	GRAND TOTAL		1,453.90	1,123.90
RECOMMENDED COST OF REPAIRS				1,123.90

Report Ref No. CS/AGI23003358/Uqy3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.