

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

60 W	DES AUTOMO	OTIVE SERVICES PTE LTD			
		THE OUNTION TO THE CID	Ref:	CS/SMR23003568/Any3e2	
E4SIN	OODLANDS I NGAPORE 75	NDUSTRIAL PARK 7705	Date:	14/06/2023	
			Code	SMR	
1. Policy Particulars :- THIRD PARTY CLAIM					
Insur	red Veh.	SHF 233T	Veh. Inspected	GBD 6742H	
Polic	y No.		Coverage (\$)	0.00	
Clain	n No.	TAX/04/23/2007	Excess (\$)	0.00	
Assig	gn From	HUA YEN	Assign Date	05/04/2023	
2. Vehicle Particulars & Condition					
Make	& Model	TOYOTA HIACE	c.c	2982	
Engi	ne No.	HIDDEN	Year of Reg.	2015	
Chas	sis No.	KDH2010146797	Colour	SILVER	
Odor	neter	204742 KM	Steering	IN ORDER	
Brak	es	IN ORDER	Modification	NIL	
Gene	eral	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
R/H F	Front Tyre	195 R15C	BRIDGESTONE	6 mm	
L/H F	Front Tyre	195 R15C	BRIDGESTONE	6 mm	
R/H F	Rear Tyre	195 R15C	BRIDGESTONE	6 mm	
L/H F	Rear Tyre	195 R15C	BRIDGESTONE	6 mm	
4. Description of Damages					
THE \	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMA	DAMAGES SEE DETAILS.				
5. General Information					
Accid	dent Date	04/04/2023	Inspection Date	05/04/2023	
Surv	ey held at	SM AUTOMOTIVE			
	BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883				
5a. Remarks					
A)THE B)IN A	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	D. Estimate Days of Repair				
ESTIN	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				