

ASS. REC. BY:

REF:

AGL 23 003570/knyz

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

05

days

Res.: Yes or No

Lum Sum: _____

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

GBF-9601B

Yr Regn: _____

05, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Toy Dyno

C.C

2982

Colour: _____

Silver

A/C: _____

Insured / Std / NI / NA

Sp. Reading: _____

232078

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

JTFA T35490K 208059

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: Triangle

195R 15XB

R: Max mile

155R 12XB(01)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. _____

9

mm

R/Bal. _____

9

mm

L/Bal. _____

9

mm

L/Bal. _____

9

mm

D.O.A. _____

4/4/23

D.O.I. _____

10/4/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

12/4 / 1 Pm @ 3400 Cahr

1 P/4/23 (Red. \$ 3263.13, 49%)

Date/Time, File Pass to?



: Prel. Report

1) 20/4/23



: Final Report

Date/Time, File Return to?

Days Of Repair: _____

5

Resurvey No. of Trip: _____

1

Survey Fee: _____

Transportation: _____

S + RS. \$

Fixes

Others

TOTAL

Add Fee: _____



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$) _____

CHEONG CHEONG MOTOR SERVICE PTE LTD

BLK 5032 ANG MO KIO IND. PARK 2 #01-293 SINGAPORE 569535

TEL : 6481 4152 FAX : 6481 4157

e-mail : c2msvc@singnet.com.sg

Our Ref : 081/04/2023

Page : 1

Date : 05/04/2023

M/S : AUTO & GENERAL INSURANCE SINGAPORE PL
190 CLEMENCEAN AVE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

ACCIDENT REPAIR ON : GBF 9601 B - TOYOTA DYNA 150
CHASSIS NO :
DATE OF ACCIDENT : 04/04/2023

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED :-

REPLACEMENT OF PARTS

- 1 TAILGATE
- 2 REAR STICKER "TOYOTA"
- 3 END PANEL 495.10
- 4 REVERSE SENSOR
- 5 SPARE TYRE BRACKET
- 6 TAILAMP LEFT
- 7 TAILAMP RIGHT
- 8 REAR NUMBER PLATE
- 9 REAR NUMBER PLATE BRACKET
- 10 REAR SUSPENSION LEFT
- 11 REAR SUSPENSION RIGHT
- 12 COIL SPRING BRACKET LEFT
- 13 COIL SPRING BRACKET RIGHT
- 14 REAR EXHAUST PIPE
- 15 REAR EXHAUST BOX

	S\$	S\$
Bj 1,057.23		
nu 80.00		
Bj 987.50		
S/NETT		250.00 200.00
nu 165.40		
cm 253.20		
lu 253.20	X	
S/NETT		20.00
S/NETT		124.50
Bj 282.00	X	
Bj 282.00	X	
Bj 160.00	X	
Bj 160.00	X	
Bj 187.00	X	
Bj 486.50	X	
4,354.03		
LESS: 10%		
435.40		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price is subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3,918.63
4,313.13

LABOUR CHARGES :

- 16 STRIP / REFIT UNDERCARRIAGE ACCESSORIES
- 17 KNOCKING PUSH OUT REAR ACCIDENT PARTS CUT & WELD END PANEL STRIP / REFIT ABOVE ACCESSORIES
- 18 SPRAY PAINT & ANTI-TUFF-KOTE ON REAR ACCIDENT DAMAGE AREAS

nu 300.00 200
1,100.00 600
950.00 550
6,663.13

