

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 9601B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE	BENT	1,057.23	1,057.23
1	REAR STICKER 'TOYOTA'	NECESSARY	80.00	80.00
1	END PANEL	BENT	987.50	495.10
1	SPARE TYRE BRACKET	MISSING	165.40	165.40
1	TAILAMP LEFT	CRACKED	253.20	253.20
1	TAILAMP RIGHT	SERVICEABLE	253.20	-
1	REAR SUSPENSION LEFT	BENT	282.00	282.00
1	REAR SUSPENSION RIGHT	BENT	282.00	282.00
1	COIN SPRING BRACKET LEFT	SERVICEABLE	160.00	-
1	COIN SPRING BRACKET RIGHT	BENT	160.00	160.00
1	REAR EXHAUST PIPE	BENT	187.00	187.00
1	REAR EXHAUST BOX	BENT	486.50	486.50
	LESS 10% DISCOUNT		-435.40	-
	LESS 25% DISCOUNT		-	-862.11
			3,918.63	2,586.32
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR (SN)	DENTED	250.00	200.00
1	REAR NUMBER PLATE (SN)	DENTED	20.00	20.00
1	REAR NUMBER PLATE BRACKET (SN)	BENT	124.50	124.50
			394.50	344.50
	<u>LABOUR</u>			
	STRIP /REFIT UNDERCARRIAGE ACCESSORIES .		300.00	200.00
	KNOCKING PUSH OUT REAR ACCIDENT PARTS CUT & WELD END PANEL STRIP /REFIT ABOVE ACCESSORIES .		1,100.00	600.00
	SPRAY PAINT & ANTI-TUFF-KOTE ON REAR ACCIDENT DAMAGE AREAS .		950.00	550.00
			2,350.00	1,350.00
	GRAND TOTAL		6,663.13	4,280.82

Report Ref No. CS/AGI23003570/Kny3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,400.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/AGI23003570/Kny3q2

KONG SENG CHEONG

Licensed Appraiser