



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI23003570/Kny3q2 Date: 24/04/2023 Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLW 189B	Veh. Inspected	GBF 9601B	
Policy No.	P10741496R00	Coverage (\$)	0.00	
Claim No.	C10021499 /SR	Excess (\$)	0.00	
Assign From	FRAULEINE KHOO	Assign Date	05/04/2023	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTFAT35Y90K208059	Colour	SILVER	
Odometer	232078 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	TRIANGLE	9 mm	
L/H Front Tyre	195 R15X8	TRIANGLE	9 mm	
R/H Rear Tyre	155 R12X8 (D)	MAXMILER	9/9 mm	
L/H Rear Tyre	155 R12X8 (D)	MAXMILER	9/9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/04/2023	Inspection Date	10/04/2023	
Survey held at	CHEONG CHEONG MOTOR SERVICE PL BLK 5032 ANG MO KIO INDUSTRIAL PARK 2 #01-293 SINGAPORE 569535			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	