

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No. 19900/190K GS1 Reg. No. 19-900/190-K				
Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAI	L INSURANCE (S) PL	F	Ref:	CS/AGI23003573/Kvy3e2
190 CLEMENCEAU	J AVENUE #03-01	[Date:	18/04/2023
		(Code:	AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKC 7282K	Veh. Inspected		SLZ 2060J
Policy No.	P10359867R02	Coverage (\$)		0.00
Claim No.	C10021479 /CH	Excess (\$)		0.00
Assign From	FRAULEINE KHOO	Assign Date		05/04/2023
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS (A)	c.c		1497
Engine No.	HIDDEN	Year of Reg.		2009
Chassis No.	MR053HY9305116321	Colour		METALLIC BLACK
Odometer	214458 KM	Steering		IN ORDER
Brakes	IN ORDER	Modification		STANDARD ALLOY RIM
General	GOOD			
3. Conditions of Tyres				
	Size	Make		Balance
R/H Front Tyre	185/60 R15	FIRENZA		6 mm
L/H Front Tyre	185/60 R15	FIRENZA		6 mm
R/H Rear Tyre	185/60 R15	FIRENZA		5 mm
L/H Rear Tyre	185/60 R15	FIRENZA		5 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/04/2023	Inspection Date		13/04/2023
Survey held at	160 SIN MING DRIVE AUTOCITY #06-01			
Repairer	SQM PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
	Insured Veh. Policy No. Claim No. Assign From Make & Model Engine No. Chassis No. Odometer Brakes General R/H Front Tyre L/H Front Tyre L/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS DAMAGES SEE D Accident Date Survey held at Repairer	AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924 Policy Particulars : Insured Veh. SKC 7282K Policy No. P10359867R02 Claim No. C10021479 /CH Assign From FRAULEINE KHOO Vehicle Partic Make & Model TOYOTA VIOS (A) Engine No. HIDDEN Chassis No. MR053HY9305116321 Odometer 214458 KM Brakes IN ORDER General GOOD Condition Size R/H Front Tyre 185/60 R15 L/H Rear Tyre 185/60 R15 Chassis No. Description THE VEHICLE SUSTAINED DAMAGES AT THE READ AMAGES SEE DETAILS. General Accident Date 01/04/2023 Survey held at 160 SIN MING DRIVE AUTOCIT Repairer SQM PTE LTD Re A)THE INSPECTION WAS CONDUCTED ON A"WIT B)IN ACCORDANCE TO YOUR INSTRUCTIONS, W	AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924 Policy Particulars: - THIRD PARTY Insured Veh. SKC 7282K Veh. Inspected Policy No. P10359867R02 Coverage (\$) Claim No. C10021479 /CH Excess (\$) Assign From FRAULEINE KHOO Assign Date Vehicle Particulars & Condition Make & Model TOYOTA VIOS (A) C.c Engine No. HIDDEN Year of Reg. Chassis No. MR053HY9305116321 Colour Odometer 214458 KM Steering Brakes IN ORDER Modification General GOOD Conditions of Tyres Size Make R/H Front Tyre 185/60 R15 FIRENZA L/H Front Tyre 185/60 R15 FIRENZA L/H Rear	AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924 Code: Policy Particulars: - THIRD PARTY CLAIM Insured Veh. SKC 7282K Veh. Inspected Policy No. P10359867R02 Coverage (\$) Claim No. C10021479 /CH Excess (\$) Assign From FRAULEINE KHOO Assign Date Vehicle Particulars & Condition Make & Model TOYOTA VIOS (A) c.c Engine No. HIDDEN Year of Reg. Chassis No. MR053HY9305116321 Colour Odometer 214458 KM Steering Brakes IN ORDER Modification General GOOD Conditions of Tyres Size Make R/H Front Tyre 185/60 R15 FIRENZA L/H Front Tyre 185/60 R15 FIRENZA L/H Rear Tyre 185/60 R15 FIRENZA MAGES SEE DETAILS. General Information Accident Date 01/04/2023 Inspection Date Survey held at 160 SIN MING DRIVE AUTOCITY #06-01 Repairer SQM PTE LTD Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISE

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: