



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGD 99L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LH/FRONT FENDER (SN)	BENT	709.96	709.96
1	FRONT BUMPER (SN)	DEFORMED	1,432.42	1,432.42
1	COMPANY SIGN (SN)	NECESSARY	81.64	81.64
1	LH/UPPER BASIC CARRIER FOR BUMPER (SN)	NECESSARY	75.68	75.68
1	RH/FRONT BASIC CARRIER FOR BUMPER (SN)	NECESSARY	74.64	74.64
1	LH/FRONT LAMP UNIT (SN)	CRACKED	3,424.13	3,424.13
1	LH/FRONT DISK WHEEL (SN)	CUT	779.44	779.44
10	RIVET FOR BUMPER (SN)	NECESSARY	53.40	53.40
			6,631.31	6,631.31
	<u>LABOUR</u>			
	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.		2,400.00	1,920.00
	RESPRAY FRONT BUMPER & LH/FRONT FENDER.		1,800.00	1,600.00
	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD.		380.00	380.00
	TO REMOVE, REPLACE HEADLAMP WITH FOCUS.		120.00	120.00
	TO INSPECT & CONDUCT WHEEL ALIGNMENT.		540.00	540.00
	LABOUR TO REMOVE AND INSTALL TYRE FROM RIM, (RUN FLAT) WHEEL BALANCE AND INSTALL NEW VALVE HEAD.		60.00	60.00
	CAVITY PRESERVATION ON REPLACED OR REPAIRED BODY PANELS PERFORM.		180.00	180.00
			5,480.00	4,800.00
	GRAND TOTAL		12,111.31	11,431.31
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)			11,431.31

Report Ref No. CS/SMR23003574/Tvy3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.