

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 044/IC/TCAC/SAY/2023
DATE : 04-APR-2023

ALLIANZ INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD #09-01

S(068897)
TEL : 63954779/67143369
FAX : 63953768
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : THERESA LOURDES
ADDRESS : 240 WESTWOOD AVENUE
#04-48
S(648364)
TELEPHONE NO : 82982164

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 2070156601-02
VEHICLE NO : SLB1434Y
MODEL CODE : TDWARDZE12EDAY407Z
MODEL/YEAR : NISSAN NOTE 1.2 BASE
ENGINE NO : HR12172950B
CHASSIS NO : JN1TAAE12Z0972209
MILEAGE : 59514 KM
DATE IN : 04/04/2023
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH
ACCIDENT DATE : 04/04/2023

Tanpin 92495749
WP' 12/4/23 @ 420 pm
r/p many before paint
tanpin e lute auto-w
12 days.

390

250

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLB1434Y

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS	60.00	bt ✓
2 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	480.00	?
3 RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	✓
4 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	500.00	?
5 WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	95.00	?
6 ZZ/001	CONDUCT 3RD PARTY CLAIM ALLIANZ DATE:04/04/2023 TIME:0728 LOCATION:PIE TOWARDS CHANGI		
7 ZZ/002	REPAIR/REPLACE RR BUMPER,ENDPANEL,FLOORPAN,TAIL GATE,LH FENDER,RH FENDER,RH DOOR & LH DOOR	3120.00	2340
8 ZZ/003	RESPRAY RR BUMPER,ENDPANEL,FLOORPAN,TAILGATE, RH FENDER,LH FENDER,RH DOOR & LH DOOR	2000.00	1750
9 ZZ/004	REMOVE/REFIX REAR UNDERCARRIAGE,FUEL TANK TO FACILITATE REPAIR	480.00	?
10 ZZ/005	REMOVE/REFIX SEAT CUSHION,GARNISH & UPHOLDERY	245.00	?
11 ZZ/006	TRANSFER TAILGATE MECHANISM TO NEW TAILGATE	120.00	✓
12 ZZ/007	REMOVE/REFIX REAR WINDSCREEN	150.00	✓
13 ZZ/008	SUPPLY/INSTALL REAR WINDSCREEN TINTED FILM	144.00	✓
14 ZZ/009	SUPPLY REVERSE SENSOR 2 EYES	250.00	✓
15 ZZ/011	CARWASH & VACUUM		
16 ZZ/012	REMOVE/REFIX EXHAUST SYSTEM TO FACILITATE REPAIR	120.00	?
17 ZZ/013	SUPPLY INSTALL REVERSE CAMERA	250.00	?
18 ZZ/014	SUPPLY/INSTALL IN CAR DVR SET	357.00	?
19 ZZ/10	QC & CONSULT CHECK		

TOTAL LABOUR CHARGES

8426.00

* To Repair Roof, Rooflining, seat, garnish needs removal to facilitate repair

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLB1434Y

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
------	----------	---------------	----------------------	------------------------------

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLB1434Y

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 WIPER ARM ASSY	28780-3VA0A ✓			91.20 <i>bt</i>
2 COVER-ARM, BACK WIPER	28782-1FC0A ✓			14.50 <i>min</i>
3 MOTOR-WIPER REAR ASSY	28710-3VA0A ✓			475.80 ?
4 LAMP ASSY-LICENCE X 2	26510-8991B ✓	178.80	<i>cur</i>	
5 STRIKER-TAIL GATE	90570-1HMOB ✓	38.70	?	
6 LOCK ASSY REAR	90502-1HM1A ✓	142.80	?	
7 ACTUATOR ASSY LOCK	90550-1HMOA ✓	189.30	?	
8 PANEL REAR LWR	79100-3VA0B ✓	616.10	<i>bt</i>	<i>phup</i>
9 LAMP COMB RR, LH	26555- ^{3VA5B} SWK0A ✓	485.20	<i>cur</i>	
10 LAMP COMB RR, RH	26550- ^{3VA5B} SWK0A ✓ <i>VB1</i>	485.20	<i>cur</i>	
11 CLIP	01553-10501 ✓	21.00	<i>ug</i>	
12 BRKT BUMPER LH	85221-3VA0C ✓	50.90	<i>dis</i>	
13 BRKT BUMPER RH	85220-3VA0C ✓	50.90	?	
14 GLASS-TAIL GATE	90300-3VA1C ✓	1333.30	<i>bno</i>	
15 ORNAMENT-BACK DOOR EMBLEM	90892-3VA0A ✓	88.80	<i>na</i>	
16 EMBLEM-BACK DOOR LETTERING	90890-3VA0A ✓	72.20	<i>ue</i>	
17 DOOR BACK	K010M-3VAMA ✓	1133.20	<i>bt</i>	
18 FACE-RR BUMPER	85022- ^{3VA0H} SWJ0H ✓	512.20	<i>de</i>	
19 ENERGY ABSORBER	85090- ^{3VA0F} SWJ0A ✓	139.60	?	
20 WEATHER STRIP	90830-3VA0A ✓	75.90	?	
21 PLATE-LUGGAGE CENTER	84992-3VA0A ✓	76.70	?	
22 FINISHER-LUGGAGE RH	84950-3VA0A ✓	441.20	?	
23 FINISHER-LUGGAGE LH	84951-3VA0A ✓	441.20	?	
24 MUFFLER ASSY REAR	20100-5WNOB ✓			595.20 ?
25 FLOOR REAR PAN	G4514-3VAMA ✓	680.90	?	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLB1434Y

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
26	BACK DOOR STAY RH PISTON	90450-3VA0A ✓	220.10 ?	
27	BACK DOOR STAY LH PISTON	90451-3VA0A -	220.10 ?	
28	BACK DOOR HINGE LH & RH	90400-1HB0A X2 ✓	96.60 ?	
29	FINISHER BACK DOOR GARNISH	90810-3VA58 BT ✓	243.90 de ✓	
30	STAY-RR BUMPER RH & LH	H5212-1HMM A X2 ✓	216.00 ?	
31	REAR W/SCREEN SEALANT	SEALANT - 4		80.00 ad ✓
32	GLASS ASSY LH QUARTER GLASS	83301-3VA3A ✓		712.60 ng ✓
33	GLASS ASSY RH QUARTER GLASS	83300-3VA3A ✓		712.60 ?
34	FENDER-REAR RH	G8100-3VAMB ✓	1012.10 ?	
35	FENDER-REAR LH	G8101-3VAMB ✓	1012.10 bu ✓	
36	DRAFTER-AIR	76804-2DZ0A ✓	75.10 ?	
SUB TOTAL			10350.10	0.00 2681.90
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			2070.02	0.00 0.00
GRAND TOTAL			8280.08	0.00 2681.90
OVERALL TOTAL			10961.98	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLB1434Y

TOTAL LABOUR CHARGES	8426.00
TOTAL SPARE PARTS CHARGES	10961.98

GRAND TOTAL	19387.98 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.