

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 6928J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER ASSY	DEFORMED	459.40	459.40
1	REAR BUMPER CENTRE MOULDING	DEFORMED	451.25	451.25
1	REAR BUMPER BEAM	NOT NECESSARY	394.80	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	BOOTLID EMBLEM - IONIQ	NECESSARY	31.30	31.30
1	BOOTLID EMBLEM - HYBRID	NECESSARY	24.30	24.30
1	BOOTLID EMBLEM - H	NECESSARY	28.00	28.00
1	FOG LAMP ASSY	NOT NECESSARY	201.50	-
1	ANTENNA SMARKEY	NOT NECESSARY	40.50	-
	LESS 20% DISCOUNT		-330.61	-203.25
			1,322.44	813.00
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN)	CRACKED	55.00	55.00
1	REVERSE SENSOR (SN)	NOT WORKING	180.00	180.00
1	REAR BOOTLID COMFORT LOGO (SN)	NECESSARY	30.00	30.00
1	REAR BOOTLID TEL.NOS LOGO (SN)	NECESSARY	30.00	30.00
1	REAR BOOTLID APPS LOGO (SN)	NECESSARY	40.00	40.00
			335.00	335.00
	<u>LABOUR</u>			
	PANEL BEATING.		400.00	350.00
	SPRAY PAINT.		600.00	500.00
	REMOVE / REFIX REVERSE SENSOR.		50.00	30.00
			1,050.00	880.00
	GRAND TOTAL		2,707.44	2,028.00





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,600.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC23003582/Tvp3m4

**MOHAMAD TAUFIKH** 

M.MATAI, AMSAE-A

**Automotive Assessor** 

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**