

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CS/AIS23003587/ANP3E2**Date:** 01/06/2023**REFERENCE**

Insured/Claimant:	SJ AUTO PTE LTD	Policy No:	SP2003057670
Date of Loss:	29/03/2023	Nature of Claim:	OD
		Claim No:	202332006936

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNB2972E	Engine No:	P520756628
Make & Model:	MAZDA 3, 1.5 (A)	Chassis No:	JM6BP2SAAM1108622
Reg. Date:	12/08/2021 (Man. Year: 2021)	Odometer:	160312 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$110,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45 R18	Rear Tyre Size:	235/45 R18
Front Left Side:	Giti 6 mm	Rear Left Side:	Giti 6 mm
Front Right Side:	Giti 6 mm	Rear Right Side:	Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,402.61	17,617.76	6,784.85	27.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,350.00	1,820.00	1,530.00	45.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,752.61	19,437.76	8,314.85	29.96
Approved Total (Overridden) (S\$)		11,500.00		
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
Nett Amount (S\$)	26,252.61	10,000.00	16,252.61	61.91

INSPECTION

Date of Assignment:	06/04/2023	SV Autoworks Pte Ltd (HQ)
Date Inspected:	06/04/2023 Inspected At:	8 Kaki Bukit Avenue 4, #02-24 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	8.0 days	

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 01 Jun 2023)
Parts: 144	MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SNB2972E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	1,380.00 FL	*1,380.00 FL
2	1		*BONNET LOCK	Not Necessary	26.00 FL	*- FL
3	2		*BONNET HINGES	Not Necessary	94.00 FL	*- FL
4	1		*FRONT GRILLE	Cracked	581.00 FL	*581.00 FL
5	1		*FRONT GRILLE BASE	Cracked	158.00 FL	*158.00 FL
6	2		*FRONT GRILLE CHROME MOULDING	Cracked	168.00 FL	*168.00 FL
7	1		*FRONT GRILLE CHROME BASE	Cracked	194.40 FL	*194.40 FL
8	1		*FRONT GRILLE EMBLEM LOGO	Cracked	68.00 FL	*68.00 FL
9	2		*FRONT GRILLE SIDE COVER	Not Necessary	139.20 FL	*- FL
10	2		*FRONT GRILLE BRACKET	Cracked	56.00 FL	*56.00 FL
11	1		*FRONT FENDER LH	Repair	428.00 FL	*- FL
12	1		*FRONT FENDER LH INNER SHIELD	Not Necessary	188.00 FL	*- FL
13	1		*FRONT FENDER LH INNER BRACKET	Not Necessary	98.40 FL	*- FL
14	1		*FRONT FENDER RH	Repair	428.00 FL	*- FL
15	1		*FRONT FENDER RH INNER SHIELD	Not Necessary	188.00 FL	*- FL
16	1		*FRONT FENDER RH INNER BRACKET	Not Necessary	98.40 FL	*- FL
17	1		*HEAD LAMP LH	Cracked	2,358.00 FL	*2,358.00 FL
18	1		*HEAD LAMP LH TOP PANEL	Repair	188.00 FL	*- FL
19	1		*HEAD LAMP RH	Cracked	2,358.00 FL	*2,358.00 FL
20	1		*HEAD LAMP RH TOP PANEL	Repair	188.00 FL	*- FL
21	1		*FRONT SUPPORT PANEL	Bent	492.00 FL	*492.00 FL
22	1		*FRONT SUPPORT PANEL TOP GARNISH	Deformed	143.00 FL	*143.00 FL
23	1		*FRONT NUMBER PLATE BASE	Deformed	135.00 FL	*135.00 FL
24	1		*FRONT BUMPER	Deformed	1,130.00 FL	*1,130.00 FL
25	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	150.00 FL	*- FL
26	1		*FRONT BUMPER FOG LAMP COVER	Not Necessary	75.00 FL	*- FL
27	1		*FRONT FOG LAMP COVER EXTENSIONS	Not Necessary	45.00 FL	*- FL
28	1		*FRONT BUMPER TOW COVER	Missing	68.00 FL	*68.00 FL
29	1		*FRONT BUMPER LOWER GRILLE	Cracked	198.00 FL	*198.00 FL
30	1		*FRONT BUMPER REINFORCEMENT	Dented	593.00 FL	*593.00 FL
31	1		*FRONT BUMPER REINFORCEMENT GARNISH	Cracked	165.00 FL	*165.00 FL
32	1		*FRONT BUMPER TOP GARNISH	Deformed	426.00 FL	*426.00 FL
33	1		*FRONT BUMPER UNDER COVER	Not Necessary	295.00 FL	*- FL
34	1		*FRONT BUMPER SUPPORT BEAM	Not Necessary	248.20 FL	*- FL
35	1		*FRONT BUMPER DUST COVER	Not Necessary	238.60 FL	*- FL
36	1		*WIPER TANK	Not Necessary	49.00 FL	*- FL
37	1		*WIPER TANK MOTOR	Not Necessary	66.20 FL	*- FL
38	1		*DASH BOARD	Torn	2,114.10 FL	*2,114.10 FL
39	1		*DASH BOARD AIR BAG	Activated	1,196.10 FL	*1,196.10 FL
40	1		*DASH BOARD AIR BAG BRACKET	Damaged	57.80 FL	*57.80 FL
41	1		*CORD SHORT AIR BAG	Activated	262.80 FL	*262.80 FL
42	1		*AIR BAG SENSOR	Activated	273.40 FL	*273.40 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*AIR BAG CONTROL UNIT	Activated	1,375.80 FL	*1,375.80 FL
44	1		*STEERING WHEEL	Not Necessary	956.30 FL	*- FL
45	1		*STEERING WHEEL SPRING CLOCK	Activated	508.70 FL	*508.70 FL
46	1		*STEERING WHEEL AIR BAG	Activated	1,539.30 FL	*1,539.30 FL
47	1		*STEERING WHEEL AIR BAG SENSOR	Activated	273.40 FL	*273.40 FL
48	1		*STEERING WHEEL AIR BAG CONTROL UNIT	Activated	1,375.80 FL	*1,375.80 FL
49	1		*FRONT RH SEAT BELT	Activated	1,074.30 FL	*1,074.30 FL
50	1		*FRONT RH SEAT BELT TENSION	Not Necessary	109.20 FL	*- FL
51	1		*FRONT LH SEAT BELT	Activated	1,074.30 FL	*1,074.30 FL
52	1		*FRONT LH SEAT BELT TENSION	Not Necessary	109.20 FL	*- FL
53	1		*SETS FRONT GRILLE CLIPS	Necessary	80.00 FS	*30.00 FS
54	2		*SETS FRONT FENDER INNER SHIELD CLIPS	Not Necessary	160.00 FS	*- FS
55	1		*SETS FRONT SUPPORT PANEL TOP GARNISH CLIPS	Necessary	80.00 FS	*30.00 FS
56	1		*FRONT NUMBER PLATE	Cracked	50.00 FS	*30.00 FS
57	1		*FRONT NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
58	1		*SETS FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
59	1		*SETS FRONT BUMPER RIVETS	Necessary	80.00 FS	*20.00 FS
60	1		*SETS FRONT BUMPER DUST COVER CLIPS	Not Necessary	80.00 FS	*- FS
61	1		*SETS FRONT GRILLE RIVETS	Necessary	80.00 FS	*20.00 FS
62	1		*SETS FRONT BUMPER TOP GARNISH RIVET	Necessary	80.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	27,022.90	21,977.20
- List Item Discount on L Items 10.00/20.00% (\$)	2,620.29	4,359.44
Total Parts (\$)	24,402.61	17,617.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	800.00	600.00
2	SPRAY	New	800.00	600.00
3	WIRING	New	100.00	30.00
4	ANTI RUST	New	100.00	30.00
5	DIAGNOSTIC	New	300.00	120.00
6	R&R RADIATOR	New	150.00	60.00
7	R&R AIR CON CONDENSER	New	200.00	60.00
8	R&R DASH BOARD ASSY	New	300.00	200.00
9	R&R BOTH FRONT SEAT BELT	New	300.00	120.00
10	R&R STEERING WHEEL	New	300.00	0.00
Gross Labour Cost (\$)			3,350.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >