

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURA	NCE BHD	Re	ef:	CS3/LPC23003590/Ua3m4	
	300 BEACH ROAD #17-04/07 THE CO) NCOURSESINGAPORE 199555	Da	ite:	10/05/2023	
			Co	de:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	YP 1900R	Veh. Inspected		GBE 1210D	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	22/23/23/VC05/027207	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		06/04/2023	
2. Vehicle Particulars & Condition						
	Make & Model	NISSAN NV200 (M)	c.c		1461	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	VSKYBAM20Z0101946	Colour		SILVER	
	Odometer	148070 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	175/70 R14	TRIANGLE		6 mm	
	L/H Front Tyre	175/70 R14	TRIANGLE		6 mm	
	R/H Rear Tyre	175/70 R14	BRIDGESTONE		6 mm	
	L/H Rear Tyre	175/70 R14	BRIDGESTONE		6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
5.	5. General Information					
	Accident Date	02/04/2023	Inspect Date / Tim	ne .	06/04/2023 (02:44 PM)	
	Survey held at	ZERO GRAVITY				
		2 KAKI BUKIT AVE 2 #01-25 KAKI BUKIT AUTOHUB SINGAPORE 417921				
5a. Remarks						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC23003590/Ua3m4

Inspected By

CHUA KANG SENG

K.K.LAU CPT(RET)

Licensed Appraiser BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser