

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT						
INCOME INSURANCE LTD			Ref:	NS/INC23003591/Nvp3e2		
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	02-05-2023 INC4		
1.						
• •	Insured Veh.	SLZ 9719Y	1	spected	SHA 1539G	
	Policy No.		Covera		0.00	
	Claim No.	MT/1217918-002	Exces		0.00	
	Assign From		Assign	,	05/04/2023	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI I40	c.c		1685	
	Engine No.	HIDDEN	Year o	f Reg.	2017	
	Chassis No.	KMHLB41UMHU098605	Coloui	•	BLUE	
	Odometer	542227	Steerii	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	GITI		8 mm	
	L/H Front Tyre	205/60 R16	GITI		8 mm	
	R/H Rear Tyre	205/60 R16	GITI		7 mm	
	L/H Rear Tyre	205/60 R16	GITI		7 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	04/04/2023	Inspec	tion Date	05/04/2023	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD					
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					