

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunoss Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS23003594/KQY3Q2**Date:** 18/04/2023**REFERENCE**

Insured/Claimant: SITI HANISAH BINTE ZAINAL ABIDIN Policy No: MPC23P00052000
Date of Loss: 03/04/2023 Nature of Claim: OD Claim No: DMPC2300227H/SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJS7556Z**
Make & Model: HONDA JAZZ, 1.3 L (A) Engine No: L13Z11015220
Reg. Date: 01/09/2009 (Man. Year: 2008) Chassis No: JHMGE68509S215222
Colour: Metallic Grey Odometer: 147843 km
Engine Capacity: 1339 cc
Market Value/New Car Price: S\$10,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15
Front Left Side: Falken 8 mm Rear Left Side: Falken 7 mm
Front Right Side: Falken 8 mm Rear Right Side: Falken 7 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 1,101.10 | 1,002.10 | 99.00 | 8.99 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,220.00 | 820.00 | 400.00 | 32.79 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (\$\$) | 2,321.10 | 1,822.10 | 499.00 | 21.50 |
| Approved Total (Overridden) (\$\$) | | 1,450.00 | | |
| (\$\$) | 2,321.10 | 1,450.00 | 871.10 | 37.53 |
| + GST 8.00/8.00% (\$\$) | 185.69 | 116.00 | 69.69 | 37.53 |
| Nett Amount (\$\$) | 2,506.79 | 1,566.00 | 940.79 | 37.53 |

INSPECTION

Date of Assignment: 05/04/2023 Present Location: Alan's United Auto Pte Ltd (HQ)
Date Inspected: 06/04/2023 Inspected At: Alan's United Auto Pte Ltd (HQ)
Estimated Period of Repair: 3.0 days Blk 7 Sin Ming Industrial Estate, #01-76
Singapore 575642

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|---------------|--|--|
| Reference | | |
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 17 Apr 2023) |
| Parts: | 144 | HONDA JAZZ 1.3 L (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SJS7556Z) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|--|-----|----------|---|-------------------|------------|-----------|
| 1 | 1 | | *FRONT RH FENDER (WCP) | Bent | 220.00 F | *220.00 F |
| 2 | 1 | | *RH HEADLAMP (WCP) | Broken | 300.00 F | *300.00 F |
| 3 | 1 | | *RH HEADLAMP LOWER BRACKET (WCP) | Distorted | 45.00 F | *45.00 F |
| 4 | 1 | | *FRONT BUMPER FASCIA (WCP) | Buckled / Cracked | 330.00 F | *330.00 F |
| 5 | 1 | | *FRONT RH BUMPER SIDE RETAINER (WCP) | Distorted | 16.00 F | *16.00 F |
| 6 | 1 | | *FRONT W/S GLASS WASHER TANK (WCP) | Serviceable | 90.00 F | *- F |
| F=Franchise part. | | | | | | |
| Sub Total (S\$) | | | | | 1,001.00 | 911.00 |
| + Margin on L,N Items 10.00/10.00% (S\$) | | | | | 100.10 | 91.10 |
| Total Parts (S\$) | | | | | 1,101.10 | 1,002.10 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|---|----------|-----------------|---------------|
| Labour Items | | | | |
| 1 | TO REWIRE DAMAGED PARTS & REFOCUS HEADLAMP BEAM | New | 20.00 | 20.00 |
| 2 | TO PUTTY AND SPRAY REPLACED PARTS | New | 700.00 | 400.00 |
| 3 | TO REMOVE ,CUT OUT DAMMAGED PARTS , PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS | New | 500.00 | 400.00 |
| Gross Labour Cost (S\$) | | | 1,220.00 | 820.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >