

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 3787T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER COVER	CRACKED	459.40	459.40
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER CENTRE MOULDING ASSY	DEFORMED	451.25	451.25
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	32.00	-
1	TAIL LAMP LH	CRACKED	935.40	935.40
1	REAR BUMPER TOWING COVER	SERVICEABLE	98.80	-
1	REAR BUMPER SIDE BRACKET LH	SERVICEABLE	55.80	-
	LESS 20% DISCOUNT		-410.93	-373.61
			1,643.72	1,494.44
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER REVERSE SENSOR (SN)	DEFORMED	180.00	180.00
			180.00	180.00
<u>LABOUR</u>				
	PANEL BEATING.		400.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	CHECK LIGHTING.		60.00	30.00
	REMOVE/REFIX REVERSE SENSOR.		80.00	30.00
			840.00	660.00
GRAND TOTAL			2,663.72	2,334.44
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,850.00

Report Ref No. NS/INC23003595/Nqp3m4



MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.