## **COMFORT TRANSPORTATION PTE LTD**

## **REPAIR ESTIMATE**

Vehicle No.: SHA3787TDate: 05/04/2023Make: HYUNDAIInsurance: INCOME

Model : IONIQ MVA: MS. LOKE YY L/S.

Qty	Parts Description / Labour	Туре	Unit Price	Amount
1	REAR BUMPER COVER / CRA			\$459.40
10	REAR BUMPER CLIPS / N \$4.			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY / DEF			\$451.25
1	REAR BUMPER REFLECTOR LH ?			\$32.0
	TAIL LAMP LH /CRA			\$935.40
1	REAR BUMPER TOWING COVER $\chi^{4\sqrt{C}}$			\$98.8
1	REAR BUMPER SIDE BRACKET LH ?			\$55.80
	SUB TOTAL			\$2,054.69
	LESS 20%			\$410.93
	DISCOUNTED TOTAL			\$1,643.7
	REAR BUMPER REVERSE SENSOR / DCf			\$180.0
			NETT	\$180.0
	Labour Charge			
	PANEL BEATING			350 \$400.0
	SPRAY PAINTING CHARGE			250 \$300.0
	CHECK LIGHTING			3 <b>\$60.</b> 0
1	REMOVE/REFIX REVERSE SENSOR			30 \$80.0
	TOTAL LABOUR			\$840.0
	ESTIMATE TOTAL			\$2,663.7
	g Krausenty Cura *			<del></del>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAZ LKIL

5/4/2023 1604

LIS

2 DAYS

CHECK ITEM PHOTOS

AFTER REPAIR PHOTOS

