

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCW 382R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT FENDER LH	BENT	342.00	342.00
1	FRONT FENDER INNER SHIELD LH	SERVICEABLE	86.00	-
1	FRONT FENDER INNER SHIELD CLIP	NOT NECESSARY	50.00	-
1	SIDE MIRROR LH	BROKEN	449.00	449.00
1	FRONT KNUCKLE ARM LH	BENT	316.00	316.00
1	FRONT WHEEL HUB LH	BENT	135.00	135.00
1	FRONT WHEEL BEARING LH	NECESSARY	118.00	118.00
1	FRONT WHEEL SPORT RIM LH	DENTED	982.00	833.00
1	FRONT STABILIZER BAR	SERVICEABLE	229.00	-
1	FRONT SHOCK ABSORBER LH	BENT	283.00	283.00
1	FRONT TIE ROD LH	SERVICEABLE	102.00	-
1	FRONT TIE ROD END LH	SERVICEABLE	80.00	-
	LESS 10% DISCOUNT		-317.20	-247.60
			2,854.80	2,228.40
	SPECIAL NETT ITEMS			
1	BRAKE FLUID (SN)	NOT NECESSARY	50.00	_
'	BIVILE I ESIB (SIV)	NOT NECESORIE	50.00	_
	LABOUR		30.00	
	<u>LABOUR</u>			
	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.		1,600.00	300.00
	TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT.		160.00	60.00
	TO REMOVE & REFIT FRONT LH UNDERCARRIAGE.		200.00	200.00
	TO REMOVE & REFIT ALL SENSOR.	NOT NECESSARY	80.00	-
	TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC).		250.00	150.00
	TO SPRAY PAINT ON THE AFFECTED AREAS.		1,000.00	280.00
			3,290.00	990.00
	GRAND TOTAL		6,194.80	3,218.40

Report Ref No. CS/FCI23003596/Kny3m4



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,550.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/FCI23003596/Kny3m4

KONG SENG CHEONG

**Licensed Appraiser**