



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581

Ref: CS/FCI23003596/Kny3m4

Date: 16/05/2023

Code: FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SG 6318H	Veh. Inspected	SCW 382R
Policy No.		Coverage (\$)	0.00
Claim No.	D23001175MFBP	Excess (\$)	0.00
Assign From	JOANNE TAN	Assign Date	05/04/2023

2. Vehicle Particulars & Condition

Make & Model	KIA CERATO K3 (A)	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KNAFZ411MJ5749411	Colour	WHITE
Odometer	142695 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45 ZR17	TOURADOR	8 mm
L/H Front Tyre	215/45 ZR17	TOURADOR	8 mm
R/H Rear Tyre	215/45 ZR17	TOURADOR	8 mm
L/H Rear Tyre	215/45 ZR17	TOURADOR	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/04/2023	Inspection Date	06/04/2023
Survey held at	160 SIN MING DRIVE #06-02 SIN MING AUTOCITY		
Repairer	MBM WHEELPOWER PTE LTD		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**