

ASS. REC. BY:

REF:

LIP / 230036011K⁹³

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Hui Yangof 0510

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 81K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SM2 8902R Yr Regn: 05, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hummer Shuttle c.c. 1496Colour: M.D. Blue A/C: Insured / Std / Nil / NASp. Reading: 151039 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: GP7 2001400Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: Giti 185/60R15R: Roadster

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 2/4/23

Survey held at

Des. of Damages: Frt / Rear / O/S / M/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

18/4 21:00pm @ 24006 Condor (Red, \$ 1401.24, 37%)

Date/Time, File Pass to?

☐ : Prel. ReportDays Of Repair: 3

1)

☐ : Final ReportResurvey No. of Trip: 2

Date/Time, File Return to?

2)

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST Reg No. 201629438M

Liberty
10/04/23
mon
Kenneth

02/04/2023

Owner: TAN YONG HENG

ESTIMATE TO REPAIR HONDA SHUTTLE HYBRID - SML6902R

1pc rear tailgate "HYBRID" emblem
1pc rear tailgate "SHUTTLE" emblem
1pc rear bumper 1050
2pcs rear bumper side retainer @\$46.50
1pc rear end panel
1pc rear end panel sensor
1pc rear end panel inner garnish

m \$ 85.20
sm \$ 85.20
Buc/m ont 1,150.60
\$ 93.00 X
\$ 601.50 X
\$ 190.50 X
\$ 195.55 X

less 20%

\$ 2,401.55
\$ 480.31
\$ 1,921.24


1set rear parking sensor

s.nett \$ 280.00 X

spray painting
labour charges
Total

\$ 800.00 400
\$ 800.00 400
\$ 3,801.24

Not Notified
21/4/23 @ 2400h
Heavy After Rain
3days



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

輝陽汽車有限公司
HUI YANG MOTORS LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Singapore 575721
Tel: 64515752 (2 Lines)
GST Reg No. 201629458

02/04/2023

Owner: TAN YONG HENG

SUPPLEMENTARY TO REPAIR HONDA SHUTTLE HYBRID - SML6902R

1pc	rear tailgate	120 R PTE	\$ 1,193.70	✓
1set	rear windscreen glass moulding		\$ 191.50	✓
		Sin Ming Drive 206	\$ 1,385.20	
		tax 64514658	\$ 277.04	
	less 20%		\$ 1,108.16	
	remove & refitt rear windscreen glass		\$ 120.00	✓
	sealant		\$ 60.00	405m
	tuffkote		\$ 60.00	301
	Total		\$ 1,348.16	

