

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 9571J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	CRACKED	459.40	459.40
1	REAR BUMPER SIDE BRACKET RH	SERVICEABLE	55.80	-
1	REAR BUMPER CENTRE MOULDING	DEFORMED	451.25	451.25
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	394.80	-
1	REAR BUMPER REINFORCEMENT STAY LH	SERVICEABLE	138.10	-
1	REAR BUMPER TOW COVER	SERVICEABLE	98.80	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-324.03	-186.53
			1,296.12	746.12
	NETT ITEMS			
1	REAR REVERSE SENSOR (N)	SERVICEABLE	180.00	_
	LESS 10% DISCOUNT		-18.00	_
			162.00	-
1	REAR NUMBER PLATE W/HOLDER (SN)	DEFORMED	55.00	30.00
	LESS 10% DISCOUNT		-5.50	-
			49.50	30.00
	SPECIAL NETT ITEMS			
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
	<u>LABOUR</u>			
	PANEL BEATING.		600.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	CHECK LIGHTING / WIRING.	NOT NECESSARY	60.00	-
	REMOVE / REFIX REVERSE SENSOR.		60.00	30.00
			1,020.00	630.00
	GRAND TOTAL		2,577.62	1,456.12

Report Ref No. NS/INC23003602/Nnp3m4





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,150.00
(TO ITS PRE-ACCIDENT CONDITION)		·
(CONFIRMED)		

Report Ref No. NS/INC23003602/Nnp3m4

**MUHAMMAD NAZRIL BIN ABDULLAH** 

**Automotive Assessor** 

T

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**