

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAllianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897**Our File No:** CC3/AIS23003605/KVY3Q2**Date:** 02/05/2023**REFERENCE**Insured/Claimant: MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE
PTE LTD

Policy No: SP2003902365

Date of Loss: 01/03/2023

Nature of Claim: OD Claim No: 202332006820

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBM1749A**Make & Model: MERCEDES-BENZ VITO, 2.2 D 112 CDI (W638)
(A)

Engine No: HIDDEN

Reg. Date: 19/12/2022 (Man. Year: 2022)

Chassis No: W1V44760324162801

Colour: White/Blue

Odometer: 3254 km

Engine Capacity: 0 cc

Market Value/New Car Price: S\$130,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17

Rear Tyre Size: 225/55 R17

Front Left Side: Dunlop 9 mm

Rear Left Side: Dunlop 9 mm

Front Right Side: Dunlop 9 mm

Rear Right Side: Dunlop 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,340.95	2,418.35	3,922.60	61.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,950.00	450.00	1,500.00	76.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,290.95	2,868.35	5,422.60	65.40
+ GST 8.00/8.00% (S\$)	663.28	229.47	433.81	65.40
Nett Amount (S\$)	8,954.23	3,097.82	5,856.41	65.40

INSPECTION

Date of Assignment: 06/04/2023

Date Inspected: 06/04/2023 Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

EXCESS: \$3,400.00

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$680.00 NETT)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 May 2023)
Parts:	M1-MPV	MERCEDES-BENZ VITO 2.2 D 112 CDI (W638) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBM1749A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP ASSY -LH	Serviceable	580.00 F	*- F
2	1		*FRONT BUMPER	Cracked	1,880.00 F	*1,880.00 F
3	1		*FRONT BUMPER REINFORCEMENT	Repair	620.00 F	*- F
4	1		*FRONT BUMPER SIDE RETAINER -LH	Serviceable	58.00 F	*- F
5	1		*FRONT BUMPER HOLDER -LH	Serviceable	58.00 F	*- F
6	1		*FRONT BUMPER ELECTRIC CHARGER INNER COVER	Cracked	78.00 F	*78.00 F
7	1		*FRONT BUMPER ELECTRIC CHARGER OUTER COVER	Missing	60.00 F	*60.00 F
8	1		*FRONT BUMPER CHARGER COVER PUSH BUTTON SWITCH	Jammed	98.00 F	*98.00 F
9	1		*FRONT BUMPER CHARGER PUSH BUTTON ACTUATOR	*Check	85.00 F	*- F
10	1		*FRONT BUMPER SOCKET ACCESS	*Check	215.00 F	*- F
11	1		*FRONT BUMPER ELECTRICAL WIRING HARNESS	Serviceable	1,950.00 F	*- F
12	15		*FRONT BUMPER CLIPS	Necessary	82.50 F	*82.50 F
						F=Franchise part.
					Sub Total (\$\$)	5,764.50 2,198.50
					+ Margin on L,N Items 10.00/10.00% (\$\$)	576.45 219.85
					Total Parts (\$\$)	6,340.95 2,418.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT AND STRAIGHTEN LH FRONT FENDER ,LH FRONT CHASSIS FRAME ,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY,TO REFIT AND ADJUST THE SAME	New	800.00	200.00
2	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	800.00	250.00
3	TO RESET & REPROGRAM ELECTRIC CHARGER WIRING SYSTEM (ONLINE) (*Check)	New	350.00	0.00
Gross Labour Cost (\$\$)			1,950.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >