



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 9905A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	TO REPAIR SEE LABOUR	550.00	-
10	REAR BUMPER CLIPS	NOT NECESSARY	35.00	-
1	REAR BUMPER BRACKET	SERVICEABLE	65.00	-
1	RHR FENDER	TO REPAIR SEE LABOUR	1,900.00	-
1	RHR TAILLAMP	BROKEN	235.00	235.00
2	TAILLAMP CLIPS	NECESSARY	15.00	15.00
1	FUEL TANK CAP	SERVICEABLE	65.00	-
	LESS 30% DISCOUNT		-859.50	-75.00
			2,005.50	175.00
<u>SPECIAL NETT ITEMS</u>				
1	ARTWORK (SN)	NECESSARY	580.00	580.00
			580.00	580.00
<u>LABOUR</u>				
	TO PANEL BEAT AND PUTTY ON RHR FENDER, REAR BUMPER.		500.00	400.00
	TO REPLACED AFFECTED PARTS.		120.00	120.00
	TO CHECK WIRING- TAILLAMP, REVERSE SENSOR.		120.00	20.00
	TO REMOVE AND REFIT REAR WINDSCREEN.	NOT NECESSARY	120.00	-
			860.00	540.00
GRAND TOTAL			3,445.50	1,295.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,050.00

Report Ref No. CS/SMR23003613/Kny3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.