

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

ECICS Limited  
10 Eunus Road 8, #09-04A Singapore Post Centre  
Singapore 408600

**Our File No:** CS4/ICS23003621/RQY3E2**Date:** 12/05/2023**REFERENCE**

Insured/Claimant: AMIRUDDIN BIN RAMLI Policy No: MPC22P00173800  
Date of Loss: 04/04/2023 Nature of Claim: OD Claim No: DMPC2300244H/ST

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SMT4585T**  
Make & Model: HYUNDAI SANTA FE, 2.4 (A) Engine No: G4KJEU352479  
Reg. Date: 30/05/2014 (Man. Year: 2014) Chassis No: KMHSU81BSEU331844  
Colour: Others Odometer: 0 km  
Engine Capacity: 2359 cc  
Market Value/New Car Price: S\$34,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: Rear Tyre Size:  
Front Left Side: 0 mm Rear Left Side: 0 mm  
Front Right Side: 0 mm Rear Right Side: 0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repaire's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	
<b>- Excess (S\$)</b>	750.00	750.00	0.00	0.00
<b>Nett Amount (S\$)</b>	<b>-750.00</b>	<b>-750.00</b>	<b>0.00</b>	<b>0.00</b>

**INSPECTION**

Date of Assignment: 06/04/2023

Date Inspected: 17/04/2023 Inspected At:

Charn's Customcraft (HQ)  
Block 1010 Bukit Merah Lane 3, #01-105  
Singapore 159724

Estimated Period of Repair: 0.0 days

**Adjuster:** MOHD RASUL**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**TOTAL LOSS ASPECT**

Market Value :	\$34,000.00
OMV :	\$25,235.00
PARF Rebate (1) :	\$15,030.00
Quota Premium Paid :	\$70,002.00
COE Rebate (2) :	\$ 7,677.00
Total Rebate (1) + (2) = :	\$22,707.00

The total amount incurred will be Market Value \$34,000.00 minus Total Rebate \$22,707.00 = \$11,293.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

# REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 May 2023)
Parts:	M1-SUV	HYUNDAI SANTA FE 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMT4585T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >