

Your Ref : DMPC2300244H/ST

Date: 12<sup>th</sup> May 2023

Our Ref : CS4/ICS23003621/Rqy3e2

**M/s ECICS Ltd**

10 Eunos Road 8

Singapore Post Centre #09-04A

Singapore 408600

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SMT 4585T  
ACCIDENT ON 04/04/2023**

Instruction was received to inspect the vehicle Reg. No. SMT 4585T. The inspection was conducted on 17/04/2023 at the premises of M/s Charn's Customcraft, Blk 1010 Bukit Merah Lane 3 #01-105, Singapore 159724.

The following vehicle information was recorded:

Registration Number	: SMT 4585T
Make/Model	: Hyundai DM Santa FE 2.4L GDI ABS D/AB SR 4WD 5DR
Year of Registration	: 2014
Body Colour	: Burnt
Chassis Number	: KMHSU81BSEU331844
Engine Capacity	: 2359 cc

The vehicle caught fire. The cause of fire probably due to engine to overheat resulting in the fire. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 34,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 22,707.00)
Nett Liability	<u>S\$ 11,293.00</u> =====

Vehicle Inspected By:



MOHAMMED RASUL BIN MOHD YUNUS  
Automotive Assessor



K.K.LAU  
MSc(Eng M), B Eng(Hons), PEng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.