



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. QX 1052R (SJS 9873U)

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BENT	836.00	836.00
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	969.00	-
1	FRONT BUMPER RETAINER	DISTORTED	42.00	42.00
1	FRONT GRILLE TOP	MTG BROKEN	588.00	588.00
1	FRONT GRILLE BOTTOM	CRACKED	928.00	928.00
1	O/S FRONT BUMPER FOG LAMP	MTG CRACKED	355.00	355.00
1	O/S FRONT BUMPER FOG LAMP COVER	MISSING	310.00	310.00
1	O/S HEAD LAMP	CRACKED	3,550.00	3,550.00
1	O/S HEAD LAMP MOULDING	SERVICEABLE	99.00	-
1	O/S FRONT FENDER INNER-SHIELD	CRACKED	89.00	89.00
	LESS 10% DISCOUNT		-776.60	-669.80
			6,989.40	6,028.20
	<u>LABOUR</u>			
	TOWING FEE.		60.00	60.00
	TO PUTTY & SPRAY PAINT.		800.00	400.00
	TO CHECK FRONT WIRING & FOCUS HEAD LAMP.		30.00	20.00
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT.		500.00	400.00
			1,390.00	880.00
	GRAND TOTAL		8,379.40	6,908.20

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,500.00
LESS EXCESS			-1,000.00
NETT LIABILITY			4,500.00

Report Ref No. CS/FCI23003630/Kny3m4

MARKET VALUE: NA -LTA REIMBURSEMENT VALUE: \$14,095.00=NETT VALUE: \$0.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.