

Lick Jess

Repair Estimate

Date: 30/03/2023

Reference:
Make:

SMX 6887M
OPEL
Crossland



To Whom It May Concern

Dear Sir,

RE: VEHICLE.: SMX 6887M
CHASSIS NO.: W0V7D9EB7L4431164
ENGINE NO.: 10Z1AE0030529

Name of insured.: LIAW CHIN WENG
Date of accident.: 28/03/2023

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts No. Qty	Part Description	Price (SGD)
1 1	FRT FENDER RH <i>But</i>	769 00
2 1	FRT FENDER SIGNAL LAMP RH ?	146 00
3 1	FRT FENDER BRACKET RH ?	130 00
4 1	FRT FENDER INNERSHIELD RH <i>deform</i>	224 00
5 1	FRT FENDER WHEELARCH GARNISH RH - Rear <i>missing</i>	247 00
6 1	FRT BUMPER <i>iron</i>	1568 00
7 1	FRT BUMPER LOW GARNISH (silver) <i>X NSP</i>	420 00
8 1	FRT BUMPER WHEELARCH GARNISH RH - Front <i>missing</i>	118 00
9 1	FRT BUMPER GRILLE RH <i>X NN</i>	166 00
10 1	FRT BUMPER GRILLE CHROME MLDG RH <i>X NN</i>	262 00
11 1	FRT BUMPER GRILLE EXTENSION MLDG RH <i>X NN</i>	114 00
12 1	FRT BUMPER GRILLE LH <i>X NN</i>	166 00
13 1	FRT BUMPER GRILLE CHROME MLDG LH <i>X NN</i>	262 00
14 1	FRT BUMPER GRILLE EXTENSION MLDG LH <i>X NN</i>	114 00
15 1	FRT BUMPER TOW COVER <i>X NN</i>	90 00
16 1	FRT BUMPER LOWER CENTRE GRILLE <i>X NN</i>	358 00
17 1	FRT BUMPER LOWER CENTRE GRILLE CENTRE COVER <i>X NN</i>	126 00
18 1	FRT BUMPER CLIP <i>N&C</i>	65 00
19 1	FRT BUMPER SIDE RETAINER LH - Guide <i>X NN</i>	142 00
20 1	FRT BUMPER SIDE RETAINER RH - Guide ?	142 00
21 1	FRT BUMPER SPONGE UPP ?	330 00
22 1	FRT BUMPER REINFORCEMENT UPP - Crash Limiter ?	933 00
23 1	FRT BUMPER REINFORCEMENT LOW - Frt End ?	882 00
24 1	FRT BUMPER REINFORCEMENT LOW STAY ?	273 00
25 1	FRT BUMPER REINFORCEMENT LOW STAY ?	273 00
26 1	FRT BUMPER UNDER DUST COVER ?	231 00
27 1	FRT BUMPER FOG LAMP COVER RH <i>scr</i>	168 00
28 1	FRT BUMPER FOG LAMP RH ?	288 00
30 1	FRT BUMPER PARKING SENSOR - Inner <i>X ?</i>	513 00
31 1	FRT BUMPER BLIND SPOT - Outer ?	280 00
32 1	FRT RADIATOR GRILLE ASSY ?	900 00
33 1	FRT RADIATOR GRILLE LOGO ?	264 00
34 1	FRT RADAR MODULE <i>X NN</i>	2035 00
35 1	FRT RADAR MODULE BRACKET <i>X NN</i>	116 00
36 1	RH HEADLAMP <i>174</i>	4312 00
37 1	FRT RADIATOR SUPORT PANEL TOP GARNISH ?	431 00
38 1	FRT RADIATOR SUPORT PANEL TOP CENTRE - Xmember ?	447 00
39 1	FRT RADIATOR SUPORT PANEL LOW CENTRE ?	180 00
40 1	FRT RADIATOR SUPORT PANEL RH ?	182 00
41 1	FRT RADIATOR SUPORT PANEL LH <i>X NN</i>	182 00
42 1	FRT DOOR RH <i>X NN</i>	2,331 00
Parts Total:		21,199.00
Less 10%:		2,119.90
Total:		19,079.10

Labour

No.	Labour Description
1	To dismantle / remove the accident damaged portion to panel beating reshape, straighten orientate and align repair / replacement parts
2	Carry out spray painting on accident affected area (R/H fender & front bumper)
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair
4	To conduct 4 wheel alignment
5	To remove and refit front sensor
6	To remove and refit aircon condensor, vacuum, refill and check air con gas system
7	To remove and refit radiator and conduct pressure test
8	To conduct H/ight alignment

Price (SGD)

2500.00 **650**

1800.00 **400 550**

80.00 **30**

150.00 **30**

100.00 **30**

880.00 **?**

80.00 **X**

80.00 **X**

Labour Total :

4,630.00

Other

No.	Other Description	Price (SGD)
1	FRT FENDER WHEELARCH CLIP	50.00
2	FRT FENDER INNERSHIELD CLIP - Rivet	50.00

Other Total :

100.00

Total : \$23,809.10
Gst (8%) : \$1,904.73
GRAND TOTAL: \$25,713.83

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor
William Wong
DID: 69223282 EXT 343



EXC: \$1250

5 days

P/P ~~1/5~~

27/4/23

11 am



**AUTO
GERMANY
PTE LTD**

Main Showroom (3S)
7 Ubi Close, Alpine Centre
Singapore 408604
Tel : (65) 6922 3288
Fax : (65) 6922 3289

Central Showroom
1 Kung Chong Road
Singapore 159139
Tel : (65) 6266 2622
Fax : (65) 6266 2522

Service Tel : (65) 6922 3282
Service Fax : (65) 6922 3283
Parts Tel : (65) 6922 3285
Parts Fax : (65) 6922 3286

Email : enquiry@autogermany.sg
Web : opel.com.sg