

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
|---|--|--|-----------------|-----------------------|--|
| | MS FIRST CAPITA | AL INSURANCE LTD | Ref: | CS/FCI23003641/Rvy3m4 | |
| | 16 RAFFLES QUA #42-01 HONG LEC SINGAPORE 0485 | ONG BUILDING | Date: | 29/05/2023 | |
| | | | Code: | FCI2 | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SMB 3509R | Veh. Inspected | SBS 8760M | |
| | Policy No. | D-22099187MFBP | Coverage (\$) | 0.00 | |
| | Claim No. | D23001197MFBP | Excess (\$) | 0.00 | |
| | Assign From | AINI BINTE | Assign Date | 10/04/2023 | |
| 2. | Vehicle Particulars & Condition | | | | |
| | Make & Model | SCANIA KUB4X2 9.3L | c.c | 9290 | |
| | Engine No. | HIDDEN | Year of Reg. | 2009 | |
| | Chassis No. | YS2K4X20001865364 | Colour | MULTI | |
| | Odometer | 1035714 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | Modification | NIL | |
| | General | FAIR | | | |
| 3. | Conditions of Tyres | | | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | 275/70 R22.5 | PIRELLI | 8 mm | |
| | L/H Front Tyre | 275/70 R22.5 | PIRELLI | 8 mm | |
| | R/H Rear Tyre | 275/70 R22.5 (D/D) | PIRELLI | 8/8 mm | |
| | L/H Rear Tyre | 275/70 R22.5 (D/D) | PIRELLI | 8/8 mm | |
| 4. | Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. | | | | |
| | DAMAGES SEE DETAILS | | | | |
| 5. | General Information | | | | |
| | Accident Date | 05/04/2023 | Inspection Date | 11/04/2023 | |
| | Survey held at | SBS TRANSIT LTD (Branch) | | | |
| | | BUKIT BATOK ST 23 SINGAPORE 659519 | | | |
| 5a. | Remarks | | | | |
| | A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | Estimate Days of Repair | | | | |
| | ESTIMATED NOR | ESTIMATED NORMAL PERIOD FOR REPAIR: 1 Working Days | | | |