



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGR 2212P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	HEADLAMP LH (WCP) }	CRACKED	2,000.00	1,900.00
1	HEADLAMP LOWER BRACKET LH (WCP) }		500.00	-
1	FRONT GRILLE (WCP)	CRACKED	580.00	580.00
1	FRONT GRILLE EMBLEM (WCP)	NOT NECESSARY	80.00	-
1	FRONT BUMPER FASCIA (WCP)	DISTORTED	2,150.00	2,150.00
1	SET FRONT BUMPER CLIPS (WCP)	NOT NECESSARY	50.00	-
1	FRONT BUMPER WASHER JET (WCP)	CRACKED	150.00	100.00
1	FRONT BUMPER WASHER JET COVER (WCP)	TWISTED	50.00	50.00
1	FRONT BUMPER FOG LAMP (WCP)	CRACKED	480.00	480.00
1	FRONT BUMPER FOG LAMP COVER (TOP) (WCP)	MISSING	60.00	60.00
1	FRONT BUMPER FOG LAMP COVER (LOWER) (WCP)	NOT NECESSARY	30.00	-
1	FRONT WHEEL ARCH GARNISH LH (WCP)	DEFORMED	220.00	220.00
1	BONNET (WCP)	TO REPAIR SEE LABOUR	3,500.00	-
2	BONNET EMBLEM (RANGE-ROVER) @\$100.00 (WCP)	SCRATCHED	200.00	200.00
1	FRONT BUMPER BEAM (WCP)	TO REPAIR SEE LABOUR	1,100.00	-
1	FRONT BUMPER SPONGE (WCP)	TORN	350.00	350.00
1	FRONT BUMPER BRACKET (WCP)	CRACKED	45.00	30.00
2	FRONT BUMPER SENSOR @\$240.00 (WCP)	SHORTED (1PC ONLY)	480.00	230.00
1	FRONT NUMBER PLATE GARNISH (WCP)	BENT	50.00	50.00
1	FRONT BUMPER LOWER TOW COVER (WCP)	DISTORTED	240.00	240.00
1	RADIATOR (ADDITIONAL) (WCP)	HOLDER LOWER BROKEN	650.00	650.00
1	SUPPORT PANEL LOWER (ADDITIONAL) (WCP)	BENT	220.00	220.00
1	FRONT SUPPORT REINFORCEMENT LH (ADDITIONAL) (WCP)	BENT	60.00	60.00
1	OVERFLOW TANK PIPE (ADDITIONAL) (WCP)	TORN	105.00	105.00
1	AIR GUIDE GARNISH (ADDITIONAL) (WCP)	TORN	80.00	80.00
	COST PLUS 10%		1,343.00	775.50
			14,773.00	8,530.50

Report Ref No. CS/GAI23003644/Uny3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT NUMBER PLATE (SN)	BENT	50.00	40.00
			50.00	40.00
	<b><u>LABOUR</u></b>			
	CUT OUT, RENEW, KNOCKING & WELDING FRONT SUPPORT PANEL, REMOVE & INSTALL ALL DAMAGE PARTS & RE-ALIGN BODY. INCLUSIVE OF THE REPAIR OF BONNET AND FRONT BUMPER BEAM.		980.00	800.00
	REMOVE & INSTALL FRONT BUMPER SENSOR.		100.00	50.00
	SPRAY PAINTING ON DAMAGE PARTS.		1,280.00	700.00
	DIAGNOSIS & RESET.		300.00	100.00
	CHECK ALL LIGHTING AFTER REPAIRS.		35.00	20.00
			2,695.00	1,670.00
<b>GRAND TOTAL</b>			<b>17,518.00</b>	<b>10,240.50</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>10,240.50</b>
<b>LESS EXCESS</b>				<b>-700.00</b>
<b>NETT LIABILITY</b>				<b>9,540.50</b>

Report Ref No. CS/GAI23003644/Uny3e2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.