

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS23003647/ANY3Q2**Date:** 25/04/2023REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SMN7331X **Insured Vehicle No :** SND8970K

Date of Loss: 06/04/2023 Nature of Claim: TP Claim No: DMPC2300245H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN7331X**

Make & Model: ADIVA AD1 200, 190cc 3W Engine No: 3A92UHT2279

Reg. Date: 27/08/2019 (Man. Year: 2019) Chassis No: MMBSTA13AKH001929

Colour: Maroon Odometer: 66833 km

Engine Capacity: 1193 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,768.00	3,314.00	3,454.00	51.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,880.00	4,680.00	7,200.00	60.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,648.00	7,994.00	10,654.00	57.13
+ GST 8.00/8.00% (S\$)	1,491.84	639.52	852.32	57.13
Nett Amount (S\$)	20,139.84	8,633.52	11,506.32	57.13

INSPECTION

Date of Assignment: 06/04/2023

Date Inspected: 10/04/2023 Inspected At: CYCLE & CARRIAGE.FULCO MOTOR DEALER
PL
NO.330 UBI ROAD 3
SINGAPORE 408650

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 24 Apr 2023)	
Parts:	N/A	ADIVA AD1 200 190cc 3W (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN7331X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*C&C BADGE	Necessary	50.00 FS	*50.00 FS
2	1		*MIVEC EMBLEM	Necessary	50.00 FS	*50.00 FS
3	1		*SET REAR REVERSE SENSOR	Damaged	220.00 FS	*220.00 FS
4	1		*REAR REVERSE CAMERA LENS	Not Necessary	380.00 FS	*- FS
5	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS
6	1		*FACE ,RR BUMPER	Deformed	919.00 FS	*919.00 FS
7	10		*CLIP ,RR BUMPER	Necessary	40.00 FS	*40.00 FS
8	1		*BRACKET ,RR BUMPER ,LH	Damaged	25.00 FS	*25.00 FS
9	1		*BRACKET ,RR BUMPER ,RH	Not Necessary	25.00 FS	*- FS
10	1		*LH REFLECTOR	Not Necessary	20.00 FS	*- FS
11	1		*BODYKITS	Cracked	1,643.00 FS	*1,643.00 FS
12	1		*BUZZER ,KEYLESS OPERATIO RR	Damaged	94.00 FS	*94.00 FS
13	1		*ANT ,KEYLESS OPERATION ,RR	Not Necessary	99.00 FS	*- FS
14	1		*COVER ,RR VENTILATOR	Not Necessary	36.00 FS	*- FS
15	3		*CLIP ,GEARSHIFT CONTROL LIN	Not Necessary	9.00 FS	*- FS
16	1		*DUCT ,RR VENTILATOR	Not Necessary	31.00 FS	*- FS
17	1		*MUD GUARD ,RR LH	Not Necessary	37.00 FS	*- FS
18	1		*MUD GUARD ,RR LH	Not Necessary	37.00 FS	*- FS
19	1		*PANEL ,RR END	Repair	440.00 FS	*- FS
20	1		*TRIM ,RR END	Not Necessary	68.00 FS	*- FS
21	1		*BOARD ,TRUNK ROOM FLOOR	Not Necessary	201.00 FS	*- FS
22	1		*WEATHERSTRIP ,TRUNK LID	Cut	161.00 FS	*161.00 FS
23	1		*PANEL ,TRUNK LID	Repair	820.00 FS	*- FS
24	1		*MARK ,THREE-DIA	Necessary	63.00 FS	*63.00 FS
25	1		*MARK,ATTRAGE	Necessary	19.00 FS	*19.00 FS
26	1		*GARNISH ,RR END PANEL	Not Necessary	346.00 FS	*- FS
27	1		*LATCH ,TRUNK LID	Not Necessary	224.00 FS	*- FS
28	1		*LAMP ASSY ,COMB,RR LH	Not Necessary	661.00 FS	*- FS
Total Parts (S\$)					6,768.00	3,314.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO APPLY SEALANT KIT ON NEW PANEL	New	240.00	0.00
2	TO APPLY ANTI-CORROSION ON REAR ACCIDENT AFFECTED AREAS	New	200.00	100.00
3	TO CHECK AND TEST REAR REVERSE SENSOR	New	100.00	100.00
4	TO REPLACE REAR BODY KIT	New	800.00	0.00
5	TO TRANSFER TRUNK LID COMPONENT AND MECHANISM PARTS	New	640.00	0.00
6	TO REMOVE AND REINSTALL TRIMMING AND CAPERTING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS	New	640.00	320.00
7	TO REPLACE REAR BUMPER ,TRUNK LID PNL ,ETC .TO CUT & REWELD REAR END PANEL,TO REPAIR REAR FLOORING AND BOTH REAR OTR QTR PNL STRAIGHTEN ,PERFORM ,ALIGN ON REAR ACCIDENT AFFECTED AREAS	New	4,480.00	1,600.00
8	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS	New	4,400.00	2,200.00
9	TO CONDUCT DIAGNOSTIC CHECK ON USING MUT TESTER AND CLEAR TROUBLE CODE	New	280.00	280.00
10	CHECK WIRING & ELECTRICAL SYSTEM	New	100.00	80.00
Gross Labour Cost (S\$)			11,880.00	4,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >