

CS/ICS23003647/Any3

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

N/S	O/S

(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 5 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SMN7331X Yr Regn: 2019, Augnt.  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Mit Attrage C.C. 1193  
 Colour: Maroon A/C: Insured / Std / NI / NA  
 Sp. Reading: 66833 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: MMBSTA13AKH001929.  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Mod: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 185/55R15.  
 R: 185/55R15.  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front 06 mm Rear 06 mm  
 R/Bal. 06 mm L/Bal. 06 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 10/04/23.  
 Survey held at Cycle and Carriage Ubi.  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
TP ECICS.

MV : We will be advising our principal a cost of repair of \$7,994.00  
 PV : before GST with 5 days of repair,  
 Nett : (red, \$10654.57%)

Date/Time, File Pass to?

1) 19/04/23

Date/Time, File Return to?

2)

Report Format:

1) 19/04/23

☐ : Preli. Report  
☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Inve (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

3 + RS. \$ \_\_\_\_\_

Photos

Other





CYCLE &amp; CARRIAGE

CYCLE &amp; CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722

MITSUBISHI  
MOTORS

Co Reg No : 197701469G

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TAN BOON KAI, DARYL (CHEN WENKAI)	Cust No/Name /TAN BOON KAI, DARYL (CHEN WENKA
BLK 273B PUNGGOL PLACE	Reg No/Reg Date SMN7331X / 27/08/2019
#10-872	Date In/Mileage 06/04/2023/ 0
SINGAPORE 822273	Chassis No MMBSTA13AKH001929
Contact No Mobile: 91111182	Engine No 3A92UHT2279
	Make/Model MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	06/04/2023/ 12:14	LER	972 / Mars Ler	15732
Description of Goods / Services					Qty Unit Price Disc% Amount
Z TEXT					
ACCIDENT ON 06/04/2023 ALONG KPE					
OWNER CLAIMING THIRD PARTY					
REQUIRED REPLACEMENT CAR					
TP # SND8970K TP INS: ECICS					
M SUNDRY					✓ 50.00
C&C BADGE					✓ 50.00
M SUNDRY					?
MIVEC EMBLEM					240.00
M SUNDRY					100.00
TO APPLY SEALANT KIT ON NEW PANEL					200.00
M SUNDRY					100.00
TO APPLY ANTI-CORROSION ON REAR ACCIDENT AFFECTED AREAS					220.00
E PNT88000					380.00
TO CHECK AND TEST REAR REVERSE SENSOR					800.00
E PNT88000					640.00
TO SUPPLY REAR REVERSE SENSOR SET					640.00
E PNT88000					320.00
TO SUPPLY REAR REVERSE CAMERA LENS					4480.00
E PNT88000					1650.00
TO REPLACE REAR BODY KIT					
E PNT88000					
TO TRANSFER TRUNK LID COMPONENT AND MECHANISM PARTS					
E PNT88000					
TO REMOVE AND REINSTALL TRIMMING AND CAPERTING TO GIVE WAY					
ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS					
E PNT88000					
TO REPLACE REAR BUMPER, TRUNK LID PNL, ETC					
-TO CUT & REWELD REAR END PANEL					
-TO REPAIR REAR FLOORING AND BOTH REAR OTR QTR PNL					
STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS					
E PNT98000					
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS					

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

## CYCLE &amp; CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722

MITSUBISHI  
MOTORS

## ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TAN BOON KAI, DARYL (CHEN WENKAI)	Cust No/Name /TAN BOON KAI, DARYL (CHEN WENKA
BLK 273B PUNGGOL PLACE	Reg No/Reg Date SMN7331X / 27/08/2019
#10-872	Date In/Mileage 06/04/2023/ 0
SINGAPORE 822273	Chassis No MMBSTA13AKH001929
Contact No Mobile: 91111182	Engine No 3A92UHT2279
	Make/Model MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00040	Cash	06/04/2023/ 12:14	LER	972 / Mars Ler	15732			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
A 10028901								280.00
TO CONDUCT DIAGNOSTIC CHECK ON USING MUT TESTER AND CLEAR TROUBLE CODE								80 100.00
A 54900099								30 50.00
CHECK WIRING & ELECTRICAL SYSTEM								
M SUNDRY <i>New</i>								
SUNDRIES								
M	FACE,RR BUMPER	<i>Repld</i>			1.00	919.00	00.00	919.00
M	CLIP,RR BUMPER	<i>New</i>			10.00	4.00	00.00	40.00
M	BRACKET,RR BUMPER,LH	<i>Repld</i>			1.00	25.00	00.00	25.00
M	BRACKET,RR BUMPER,RH	<i>New</i>			1.00	25.00	00.00	25.00
M	LH REFLECTOR	<i>?</i>			1.00	20.00	00.00	20.00
M	BODYKITS	<i>Repld</i>			1.00	1643.00	00.00	1643.00
M	BUZZER,KEYLESS OPERATIO,RR	<i>?</i>			1.00	94.00	00.00	94.00
M	ANT,KEYLESS OPERATION,RR	<i>?</i>			1.00	99.00	00.00	99.00
M	COVER,RR VENTILATOR	<i>?</i>			1.00	36.00	00.00	36.00
M	CLIP,GEARSHIFT CONTROL LIN	<i>?</i>			3.00	3.00	00.00	9.00
M	DUCT,RR VENTILATOR	<i>?</i>			1.00	31.00	00.00	31.00
M	MUD GUARD,RR LH	<i>?</i>			1.00	37.00	00.00	37.00
M	MUD GUARD,RR LH	<i>?</i>			1.00	37.00	00.00	37.00
M	PANEL,RR END	<i>?</i>			1.00	440.00	00.00	440.00
M	TRIM,RR END	<i>New</i>			1.00	68.00	00.00	68.00
M	BOARD,TRUNK ROOM FLOOR	<i>New</i>			1.00	201.00	00.00	201.00
M	WEATHERSTRIP,TRUNK LID	<i>Repld</i>			1.00	161.00	00.00	161.00
M	PANEL,TRUNK LID	<i>New</i>			1.00	820.00	00.00	820.00
M	MARK,THREE-DIA	<i>New</i>			1.00	63.00	00.00	63.00
M	MARK,ATTRAGE	<i>New</i>			1.00	19.00	00.00	19.00
M	GARNISH,RR END PANEL	<i>New</i>			1.00	346.00	00.00	346.00
M	LATCH,TRUNK LID	<i>New</i>			1.00	224.00	00.00	224.00
M	LAMP ASSY,COMB,RR LH	<i>?</i>			1.00	661.00	00.00	661.00
SURVEYOR NAME: <i>Adrian Lj</i>								
SURVEYOR SIGNATURE: <i>88.8</i>								
DATE: <i>10/04/23</i>								
REMARKS: <i>04 Days</i>								

Confirm &amp; accepted by

Nett 18,648.00  
8% GST on 18648.00 1491.84  
Total Payable 20,139.84

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.