Francisco Francis & F. F. 1. 72



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED Libi Customer Service Centre

Ubi Customer Service Centre330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
TAN BOON KAI, DARYL (CHEN WENKAI)	Cust No/Name	/TAN BOON KAI, DARYL (CHEN WENKA		
TAN BOOK RAI, DAKTE (CHEN WENKAI)	Reg No/Reg Date	SMN7331X / 27/08/2019		
BLK 273B PUNGGOL PLACE	Date In/Mileage	06/04/2023/ 0		
#10-872 SINGAPORE 822273	Chassis No	MMBSTA13AKH001929		
	Engine No	3A92UHT2279		
Contact No Mobile: 91111182	Make/Model	MIT/19MY ATTRAGE 1.2 CVT		
	Colour/Trim	P57 WINE RED PEARL / BK BLACK		

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No	
CTP00040	Cash	06/04/2023/ 12:14	LER	972 / Mars	Ler	15732	
		Description of Good	s / Service	s	Qty	Unit Price Disc%	6 Amount
OWNER CL REQUIRED TP # SND M SUNDRY	AIMING T REPLACE 8970K	TP INS: ECICS					~ 50.00
C&C BADG M SUNDRY	E Nu	-					50.0
MIVEC EM	IBLEM /	cu					7. 240.0
M SUNDRY	CEALANT	KIT ON NEW PANEL	7		general and the second		240.0
M SUNDRY	SEALANT	KII UN NEW PANEL		TIPES	(D)		100200-0
TO APPLY	ANTI-CO	RROSION ON REAR ACCI	DENT AFFE	CTED AREAS	73111		100.0
E PNT88000	AND TES	T REAR REVERSE SENSO	R		6166		100.0
E PNT88000	AND IES	T REAR REVERSE SENSO					7 220.0
	Y REAR R	EVERSE SENSOR SET	?				4 380.0
E PNT88000	V DEAD D	REVERSE CAMERA LENS	ud n				380.0
E PNT88000	I KLAK K	KEVERSE CAMERA ELIIS					₩ 800.0
	ACE REAR	BODY KIT					640.0 بد
E PNT88000	CED TOUR	K LID COMPONENT AND	MECHANISM	PARTS			2. 640.0
E PNT88000	OFER TRUN	IN LID COMPONENT AND	PILCHARTSI	TAKIS			320 640.0
		INSTALL TRIMMING AND					
ACCESS F E PNT88000	REPAIR ON	REAR ACCIDENT AFFEC	TED AREAS				1280 4480.0
TO REPLA		BUMPER, TRUNK LID PNL REAR END PANEL	,ETC				
		FLOORING AND BOTH RE	AR OTR OT	R PNL			
STRAIGHT		RM, ALIGN ON REAR ACCI					1650
E PNT98000	A TAITTAIC C	ON DEAD ACCIDENT AFFE	CTED ADEA	C			4400.0
SPRAY PA	AINTING (ON REAR ACCIDENT AFFE	CIED AREA	13			

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre



330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X Owner Name & Vehicle Info **Invoice Name & Address** /TAN BOON KAI, DARYL (CHEN WENKA Cust No/Name TAN BOON KAI, DARYL (CHEN WENKAI) / 27/08/2017 Reg No/Reg Date SMN7331X Date In/Mileage | 06/04/2023/ BLK 273B PUNGGOL PLACE MMBSTA13AKH001929 #10-872 Chassis No SINGAPORE 822273 3A92UHT2279 **Engine No** MIT/19MY ATTRAGE 1.2 CVT Make/Model Contact No Mobile: 91111182 P57 WINE RED PEARL / BK BLACK Colour/Trim

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
CTP00040	Cash	06/04/2023/ 12:14	LER	972 / Mars Ler		15732		
711 00040	Cusiii	Description of Goods		s	Qty	Unit Price	Disc%	Amount
A 10028901								280.00
TO CONDU	CT DIAGN	OSTIC CHECK ON USING	MUT TESTE	ER AND CLEAR TROUBLE	CODE			80 100.00
A 54900099								100.00
		LECTRICAL SYSTEM						3V 50.00
M SUNDRY SUNDRIES	New							_
M FACE, RR	BUMPER	Delic			1.00	919.00		919.00
M CLIP.RR	BUMPER	New ,			10.00	4.00		40.00 25.00
M BRACKET,	RR BUMPE	R,LH			1.00	25.00 25.00		¥. 25.00
		ER,RH We ~			1.00		00.00	20.00
M LH REFLE		0 1	一几		1.00	1643.00		✓ 1643.00
M BODYKITS			21	1110012	1.00	94.00	WEST OF THE PARTY	94.00
M BUZZER,	ESC UDE	OPERATIO,RR RATION,RR ?	5) 14	111111111111111111111111111111111111111	1.00	99.00		99.00
	R VENTILA				1.00		00.00	7 36.00
		CONTROL LIN ?			3.00		00.00	? 9.00
	VENTILA				1.00		00.00	7 31.00
	RD, RR LH				1.00		00.00	7 37.00 7 37.00
	RD, RR LH				1.00		00.00	7 440.00
M PANEL, R					1.00		00.00	+ 68.00
	END M	M FLOOR Men			1.00		00.00	+ 201.00
M BOARD, T M WEATHER	CTDID TD	UNK LID Cut			1.00		00.00	161.00
M DANEL T	DUNIV LTD	8.			1.00		00.00	820.00
M MARK, TH	REE-DIA TRAGE	2.14	4	11 .	1.00		00.00	63.00
M MARK, AT	TRAGE	INA	A	han Cj	1.00		00.00	→ 19.00 → 346.00
M GARNISH	,RR END	PANEL SURVEYOR NA	ME:		1.00		00.00	224.00
M LATCH, T	RUNK LID	re c		88.0,	1.00		00.00	661.00
M LAMP AS	SY, COMB,	RR LH ? SURVEYOR SIG	NATURE :	800	1.00	00210		•
		DATE: 100	14/13.	04 De	w.			
					1			
		REMARKS:			U			
0 6: 0		L						
Confirm &	accepted	БУ				M	ett	18,648.0
	起		:əteO		8% GST or			1491.8
			utengi2		0. 00. 0.			
		Wedged by Repairer	Acknow			Total Paya	ble	20,139.8
	cs company	oject to final approval from Insuran	ins si					
Authorize	d signato	erysand isompany i stampual	ddng •					

Validity of this estimate is required and the of quote. This is a computer generated document, no signature is required.

Estimated costsequented and record adding in the world mention that the above estimate is based on our initial inspection and does not include any additional parts or about which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repair of replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repairs and the course of the windscreen.

Page 2 of 2 **TKK Auto Consultants** hence notify

Page 2 of 2