



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722

MITSUBISHI
MOTORS

Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TAN BOON KAI, DARYL (CHEN WENKAI)	Cust No/Name /TAN BOON KAI, DARYL (CHEN WENKA
BLK 273B PUNGGOL PLACE	Reg No/Reg Date SMN7331X / 27/08/2019
#10-872	Date In/Mileage 06/04/2023/ 0
SINGAPORE 822273	Chassis No MMBSTA13AKH001929
Contact No Mobile: 91111182	Engine No 3A92UHT2279
	Make/Model MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	06/04/2023/ 12:14	LER	972 / Mars Ler	15732
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
Z TEXT					
ACCIDENT ON 06/04/2023 ALONG KPE					
OWNER CLAIMING THIRD PARTY					
REQUIRED REPLACEMENT CAR					
TP # SND8970K TP INS: ECICS					
M SUNDRY	C&C BADGE				50.00
M SUNDRY	MIVEC EMBLEM				50.00
M SUNDRY	TO APPLY SEALANT KIT ON NEW PANEL				240.00
M SUNDRY	TO APPLY ANTI-CORROSION ON REAR ACCIDENT AFFECTED AREAS				200.00
E PNT88000	TO CHECK AND TEST REAR REVERSE SENSOR				100.00
E PNT88000	TO SUPPLY REAR REVERSE SENSOR SET				220.00
E PNT88000	TO SUPPLY REAR REVERSE CAMERA LENS				380.00
E PNT88000	TO REPLACE REAR BODY KIT				800.00
E PNT88000	TO TRANSFER TRUNK LID COMPONENT AND MECHANISM PARTS				640.00
E PNT88000	TO REMOVE AND REINSTALL TRIMMING AND CAPERTING TO GIVE WAY				640.00
E PNT88000	ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS				4480.00
E PNT88000	TO REPLACE REAR BUMPER, TRUNK LID PNL, ETC				1600.00
	-TO CUT & REWELD REAR END PANEL				
	-TO REPAIR REAR FLOORING AND BOTH REAR OTR QTR PNL				
	STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS				
E PNT98000	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS				4400.00
Confirm & accepted by					
Authorized signatory and company stamp					

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

Ubi Customer Service Centre

330 Ubi Road 3, Singapore 408650 Tel: (65) 64739722



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TAN BOON KAI, DARYL (CHEN WENKAI)	Cust No/Name /TAN BOON KAI, DARYL (CHEN WENKA
BLK 273B PUNGGOL PLACE	Reg No/Reg Date SMN7331X / 27/08/2017
#10-872	Date In/Mileage 06/04/2023/ 0
SINGAPORE 822273	Chassis No MMBSTA13AKH001929
Contact No Mobile: 91111182	Engine No 3A92UHT2279
	Make/Model MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CTP00040	Cash	06/04/2023/ 12:14	LER	972 / Mars Ler	15732		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
A 10028901							280.00
TO CONDUCT DIAGNOSTIC CHECK ON USING MUT TESTER AND CLEAR TROUBLE CODE							
A 54900099							100.00
CHECK WIRING & ELECTRICAL SYSTEM							
M SUNDRY <i>new</i>							50.00
SUNDRIES							
M	FACE,RR BUMPER	<i>Deland</i>	1.00	919.00	00.00		919.00
M	CLIP,RR BUMPER	<i>new</i>	10.00	4.00	00.00		40.00
M	BRACKET,RR BUMPER,LH	<i>new</i>	1.00	25.00	00.00		25.00
M	BRACKET,RR BUMPER,RH	<i>new</i>	1.00	25.00	00.00		25.00
M	LH REFLECTOR	<i>new</i>	1.00	20.00	00.00		20.00
M	BODYKITS	<i>cauled</i>	1.00	1643.00	00.00		1643.00
M	BUZZER,KEYLESS OPERATIO,RR	<i>new</i>	1.00	94.00	00.00		94.00
M	ANT,KEYLESS OPERATION,RR	<i>new</i>	1.00	99.00	00.00		99.00
M	COVER,RR VENTILATOR	<i>new</i>	1.00	36.00	00.00		36.00
M	CLIP,GEARSHIFT CONTROL LIN	<i>new</i>	3.00	3.00	00.00		9.00
M	DUCT,RR VENTILATOR	<i>new</i>	1.00	31.00	00.00		31.00
M	MUD GUARD,RR LH	<i>new</i>	1.00	37.00	00.00		37.00
M	MUD GUARD,RR LH	<i>new</i>	1.00	37.00	00.00		37.00
M	PANEL,RR END	<i>new</i>	1.00	440.00	00.00		440.00
M	TRIM,RR END	<i>new</i>	1.00	68.00	00.00		68.00
M	BOARD,TRUNK ROOM FLOOR	<i>new</i>	1.00	201.00	00.00		201.00
M	WEATHERSTRIP,TRUNK LID	<i>new</i>	1.00	161.00	00.00		161.00
M	PANEL,TRUNK LID	<i>new</i>	1.00	820.00	00.00		820.00
M	MARK,THREE-DIA	<i>new</i>	1.00	63.00	00.00		63.00
M	MARK,ATTRAGE	<i>new</i>	1.00	19.00	00.00		19.00
M	GARNISH,RR END PANEL	<i>new</i>	1.00	346.00	00.00		346.00
M	LATCH,TRUNK LID	<i>new</i>	1.00	224.00	00.00		224.00
M	LAMP ASSY,COMB,RR LH	<i>new</i>	1.00	661.00	00.00		661.00
SURVEYOR NAME: <i>Adrian Lj</i>							
SURVEYOR SIGNATURE: <i>Adrian Lj</i>							
DATE: <i>10/04/23</i>							
REMARKS: <i>04 Days + 1 Day</i>							
Confirm & accepted by <i>Adrian Lj</i>							
Authorized signatory and company stamp							
14/04/23 8% GST on					Nett	18,648.00	
						1491.84	
					Total Payable	20,139.84	

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewal the rubber seal or other repair requiring the removal of the windscreen.