

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23003654/UYA3Q2**Date:** 31/07/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100319728
Claimant Vehicle No :	SMA8966B	Insured Vehicle No :	S3007CD
Date of Loss:	10/04/2023	Nature of Claim:	TP
		Claim No:	6031963174SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA8966B	Engine No:	L15B5552572
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11302563
Reg. Date:	22/06/2018 (Man. Year: 2018)	Odometer:	105196 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Continental 7 mm	Rear Left Side:	Continental 7 mm
Front Right Side:	Continental 7 mm	Rear Right Side:	Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,483.68	7,577.52	5,906.16	43.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,770.00	2,870.00	900.00	23.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,253.68	10,447.52	6,806.16	39.45
Approved Total (Overridden) (S\$)		8,300.00		
(S\$)	17,253.68	8,300.00	8,953.68	51.89
+ GST 8.00/8.00% (S\$)	1,380.29	664.00	716.29	51.89
Nett Amount (S\$)	18,633.97	8,964.00	9,669.97	51.89
+ Car Rental (9.0 x S\$100.00/day + 8.00% GST) (S\$)		972.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		9,938.00		

INSPECTION

Date of Assignment:	10/04/2023	
Date Inspected:	10/04/2023	Inspected At: Falcon-Air Auto Services Pte Ltd (Tampines) Blk 9006 #01-200 Tampines St 93 Singapore
Estimated Period of Repair:	8.0 days	

Adjuster: MARCUS CHUA**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	753.00 FL	*753.00 FL
2	2		*REAR BUMPER SIDE RETAINER	Not Necessary	70.00 FL	*- FL
3	2		*REAR BUMPER SIDE	Deformed / Warped	562.00 FL	*562.00 FL
4	1		*REAR BUMPER UNDERCOVER	Distorted	318.00 FL	*318.00 FL
5	1		*REAR BUZZER SENSOR	Damaged	125.00 FL	*125.00 FL
6	1		*ANTENNA ASSY -SMARTKEY	Not Necessary	123.00 FL	*- FL
7	1		*TAILGATE	Badly Dented	1,197.00 FL	*953.00 FL
8	1		*SET TAILGATE GLASS MOULDING	Necessary	168.00 FL	*118.20 FL
9	1		*TAILGATE VEZEL EMBLEM	Necessary	89.00 FL	*66.00 FL
10	1		*TAILGATE LOGO EMBLEM	Necessary	87.00 FL	*38.00 FL
11	1		*TAILGATE LOCK	Twisted	353.00 FL	*180.20 FL
12	1		*TAILGATE WEATHERSTRIP	Twisted	155.00 FL	*155.00 FL
13	1		*TAILGATE POCKET	Not Necessary	50.00 FL	*- FL
14	1		*TAILGATE TRIM BOARD	Twisted	353.00 FL	*242.30 FL
15	1		*REAR END PANEL	Badly Dented	562.00 FL	*517.00 FL
16	1		*REAR END PANEL GARNISH	Deformed	296.00 FL	*122.80 FL
17	2		*REAR FENDER INNER TRIM	Deformed / Twisted	1,520.00 FL	*732.00 FL
18	2		*REAR FENDER ARCH GARNISH	Torn	396.00 FL	*396.00 FL
19	1		*REAR COMPARTMENT BOARD	Torn	362.00 FL	*362.00 FL
20	1		*REAR COMPARTMENT SPONGE	Torn	282.30 FL	*282.30 FL
21	1		*TAILGATE LAMP	O/S Cracked	764.80 FL	*281.00 FL
22	1		*TAILLAMP	O/S Cracked	996.00 FL	*482.00 FL
23	1		*TAILGATE OUTER GARNISH	Repair	265.00 FL	*- FL
24	1		*REAR BUMPER REFLECTOR	N/S Not Necessary / O/SCracked	317.80 FL	*158.90 FL
25	1		*REAR COMPARTMENT PANEL	Crumpled / Buckled	989.70 FL	*989.70 FL
26	1		*EXHAUST HEAT SHIELD	Bent	187.50 FL	*187.50 FL
27	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
28	1		*REAR BUMPER DIFFUSER	Distorted	600.00 FS	*500.00 FS
29	1		*REAR BUMPER SCUFF PLATE	Bent	450.00 FS	*250.00 FS
30	1		*SET REAR BUMPER UNDERCOVER CLIPS	Necessary	50.00 FS	*30.00 FS
31	1		*TAILGATE GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
32	1		*TAILGATE GLASS INNER SEAL	Necessary	50.00 FS	*40.00 FS
33	1		*TAILGATE BODY SEALANT	Not Necessary	80.00 FS	*- FS
34	1		*SET TAILGATE TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
35	1		*SET REAR END PANEL GARNISH CLIP	Not Necessary	50.00 FS	*- FS
36	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	100.00 FS	*- FS
37	1		*SET TAILGATE DAMPER	Not Necessary	1,800.00 FS	*- FS
38	1		*SET REAR FENDER ARCH GARNISH CLIP	Not Necessary	50.00 FS	*- FS
39	1		*REAR NUMBER PLATE	Bent	50.00 FS	*40.00 FS
40	1		*SET REVERSE CAMERA	Serviceable	380.00 FS	*- FS
41	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
42	1		*REAR COMPARTMENT RUBBER INSULATOR	Not fitted	400.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,752.10	9,181.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,268.42	1,604.38
Total Parts (\$\$)	13,483.68	7,577.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK LIGHT AND WIRING	New	50.00	30.00
2	TRANSFER TAILGATE GLASS	New	120.00	120.00
3	TRANSFER TAILGATE PARTS	New	100.00	60.00
4	INSTALL REVERSE SENSOR IN NEW BUMPER	New	80.00	50.00
5	INSTALL REVERSE CAMERA	New	150.00	0.00
6	REMOVE /REFIT INNER TRIMS TO FACILITATE REPAIR	New	150.00	80.00
7	ANTI-RUST	New	120.00	80.00
8	TO APPLY BODY SEALANT ON BODY JOINTS	New	120.00	0.00
9	LABOUR/PANEL BEATING	New	1,500.00	1,300.00
10	SPRAY PAINTING	New	1,200.00	1,100.00
11	INSTALL TAILGATE DAMPER AND WIRING	New	180.00	50.00
Gross Labour Cost (S\$)			3,770.00	2,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >